



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1
1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SHC1128Z
CLAIM TYPE : THIRD PARTY
TP INS. CO. : HSBC LIFE (SINGAPORE) PTE LTD
ACCIDENT DATE : 06/06/2023
TP VEH REG NO : SHC1128Z

ESTIMATE

NO : QUOT202306-000012(00)
DATE : 07/06/2023
POLICY NO : SP2003902365
VEH REG NO : GBJ6248L
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323567924
ENGINE NO : 65195034993265
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ6248L

Description	Quantity	Unit Price	Amount
		S\$	S\$
LABOUR			2001
1 To panel beat LH rear fender & LH sliding and realign the same	1	600.00	600.00
2 To putty and spray LH sliding door & LH rear fender	1	600.00	600.00 4001
3 To supply and paste decal on LH rear fender and LH sliding door	1	500.00	500.00 251
4 To apply rust-proofing on repaired panels	1	120.00	120.00 X
			1,820.00
		TOTAL	S\$ 1,820.00
		ADD GST @ 8%	145.60
		GRAND TOTAL	S\$ 1,965.60

SINGAPORE DOLLAR ONE THOUSAND NINE HUNDRED SIXTY-FIVE AND CENTS SIXTY ONLY

*Not Withhold
Payment After Repair*

3 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD