

ASS. REC. BY: Tauyph

REF: CS/FC123006767/703

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9135K

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Yixin

Date / Time	Action / Instruction

Veh No: SND1639P Yr Regn: 2021, Dec.

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

☐ Truck / ☐ Trailer or

Make: Toyota C-HR Hybrid c.c. 1297

Colour: Blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

\$p. Reading: 28199 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: ZYX102178817

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: ☒ N/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/60R17

R:

BS ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIG / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 12/7/23

Survey held at

Xin Yun

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/G / ☐ Rooftop or

Rt N/S

The U/G / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.K. (T) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS + SI _____

Photos _____

Others _____



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND1639P TOYOTA C-HR Latest Model

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,085.10 <i>Ry</i>
2	1	Front bumper left bracket	\$ 88.00×
3	1	Both side foglamp cover	\$ 180.00×
4	1	Front bumper tow cover	\$ 80.00×
5	1	Wheel arch trim cover	\$ 292.40 <i>cut</i>
6	1	Wheel bearing set	\$ 383.80×
7	1	Wheel arch inner cowling	\$ 288.60×
8	1	Lower tray	\$ 298.00×
9	1	Rim	\$ 850.00×
10	1	Sensor	\$ 280.00×
11	1	Sensor harness cable	\$ 450.00×
		Parts Sub-total	\$ 4,275.00
		<i>Frt LH fender Rx</i>	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND1639P TOYOTA C-HR Latest Model

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Front bumper clips	\$ 100.00×
2	8	Front bumper lower grille clips	\$ 80.00×
3	8	Front bumper lower tray clips	\$ 80.00×
4	8	Front left fender inner cowling clips	\$ 80.00×
5	1	Front no plate with cashing	\$ 100.00×
6	2	PU420 sealer for body work	\$ 90.00×
		Special Nett Items	\$ 530.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND1639P TOYOTA C-HR Latest Model

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 1,600.00 200
2	To putty and spray painting front portion.	\$ 1,800.00 400
3	To check wiring and focus front headlamp.	\$ 80.00 X
4	To apply anti rust proofing to front affected area.	\$ 150.00 X
5	To remove and install front undercarriage parts	\$ 250.00 X
6	To balance front right wheel.	\$ 60.00 X
7	To conduct wheel alignment.	\$ 120.00 X
8	To remove and install bumper sensor.	\$ 80.00 X
9	Remove accident fault code, clear fault code	\$ 250.00 X

Total labour : \$ 4,390.00

Tanphin 97495749/6233356/

WP' 12/7/23 @ 540pm

4/5 Resurvey after repair 2-3 days

Tanphin @ huanauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during **resurvey**
- Parts prices are subject to **confirmation**
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: