

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 25 Jul 2023

Preliminary Advice

Insured Vehicle No	: FBK5487P	Accident Date	: 30/06/2023
TP Vehicle No	: GBB5802K	Assignment Date	: 11/07/2023
Make	: KIA 2900L 5	Est. Duration of Repair	: 3
Date of Inspection	: 10/07/2023		
Inspection At	: LH EXPRESS MOTOR TRADING (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,882.50
Revised Amount	:S\$	1,878.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,878.30
Lump Sum Repair	:S\$	1,500.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,000.00
COE / PARF Rebate	:S\$	2,680.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,320.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.