

L H Express Motor Trading

Bik 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 91082728

New Guan Hong Trading Pte Ltd
11 Defu Lane 4
Singapore 539414

Vehicle No : GBB 5802 K
Make/Model : Kia K 2700
Year : 2006

*Not Notwork
11Rm & 1500p
Resurvey After Paint*

3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s tail-lamp assy <i>197</i>	<i>67</i>	\$305.00 ✓
1 pc	Rear n/s tail-lamp panel <i>197</i>	<i>87</i>	\$285.00 ✓
1 pc	Rear n/s tail-lamp panel rubber stopper ✓	<i>111</i>	\$35.00 ✓
			\$625.00
		Less 10 %	\$62.50
			\$562.50

Nett Item

1 pc	Rear end panel steel plate ✓	<i>0.1</i>	\$950.00 <i>25cl</i>
1 pc	Rear n/s cabin box pillar ✓	<i>1.1</i>	\$1,200.00 <i>280cl</i>
1 pc	Rear no plate ✓	<i>3</i>	\$40.00 <i>X</i>
			\$2,190.00

Labour Charges

Remove/renew the above accident parts. Knock out & reshape rear end panel, rear n/s tail-lamp panel.	\$800.00	<i>20cl</i>
To putty and spray paint on rear accident portion.	\$600.00	<i>250cl</i>
Check & reconnect wiring.	\$30.00	<i>15cl</i>
Remove/refit rear end panel steel plate protector and to remove/renew rear n/s cabin box pillar.	\$700.00	<i>400cl</i>
Total	\$4,882.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *0* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WASTE