

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0635/2023/GW/TF
DATE : 8-Jul-23
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/2023
YOUR INSURED VEH NO : GBD 2072 J

MS First Capital Insurance Limited

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Dept

OWNER'S NAME : MR ANG YOKE PHENG
ADDRESS : 5C CHANCERY HILL RD
SINGAPORE 309647
TELEPHONE : HP +65 98399366
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SDS 5225 Y**
MODEL CODE : AUDI Q2 1.4 TFSI
MODEL YEAR : 28/9/2018
ENGINE NO : CHZA90358
CHASSIS NO : WAUZZZGA5KA0006321
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Jul-23
PLACE OF ACCIDENT : ONE NORTH AVE AT TRAFFIC LIGHT JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDS 5525 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,672.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 5525 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,442.00	
2	REAR BUMPER FIXING PARTS	1	\$ 85.00	
3	REAR BUMPER SPOILER	1	\$ 335.00	
4	REAR BUMPER COVER TOW EYE COVER	1	\$ 51.00	
5	REAR LIGHT REFLECTOR - LH / RH	2	\$ 72.00	
6	REAR REINFORCEMENT BEAM	1	\$ 653.00	
7	REAR BUMPER HOLDING STRAP - LH/RH	2	\$ 32.00	
8	REAR SENSOR - INNER / OUTER	2	\$ 543.00	
9	REAR SENSOR SEAL RING	4	\$ 11.00	
10	REAR WHEEL COVER - LH/ RH	2	\$ 380.00	
11	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			: \$ 4,004.00	
TOTAL LABOUR CHARGES			: \$ 2,672.00	
GRAND TOTAL			: \$ 6,676.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-05/06/23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT