Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

Noor Amran, Noor Yussyuhaila

#09-16

Attn:

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 24 Jul 2023

Preliminary Advice

 Vehicle No
 : SMN8238B
 Accident Date
 : 08/07/2023

 Make
 : AUDI A5
 Policy No.
 : 1900121316

 Assignment Date
 : 10/07/2023
 Excess
 : \$\$1,600.00

Date of Inspection : 21/07/2023 Est. Duration of Repair : 4

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,839.00
Revised Amount	:S\$	6,853.00
Check Items (Estimated)	:S\$	1,061.00
Total	:S\$	7,914.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 143,000.00

 COE / PARF Rebate
 :S\$ 57,773.00

Salvage Value :S\$

Margin for Repair :S\$ 85,227.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have
	your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.