

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401659H GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)



12/7/23 @ 12 pm.

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

11 JUL 2023

Estimate No. : b1 66626  
Date Estimated : 10/07/2023  
Prepared By : Simon Koh Eng Aun

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Ler Huey Ching  
Blk 234 Ang Mo Kio Avenue 3  
#09-1134

Singapore 560234

## - ACCOUNT - 158

Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| BKQ719R   | WBA3A16010NS37233 | 31/10/2014 | 316iA/4 | 96325   |

## DESCRIPTION

To replace front left door, rear left door, make good rear bumper and replace all damage attachment

1700 ~~2,550.00~~

To respray front left door, rear left door and rear bumper

2808 ~~2,956.00~~

To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (2 doors).

1008 ~~1,062.00~~

To conduct check on all doors and bootlid central locking system for proper function.

168 ~~177.00~~

To carry out body cavity preservation. (Per panel).

224 ~~236.00~~

Sundries.

? 150.00

Total Labour 1: 7,131.00

## DESCRIPTION

| DESCRIPTION                                  | QTY | PRIC     | VALUE    |
|----------------------------------------------|-----|----------|----------|
| REAR LH DOOR <i>bt</i>                       | 1   | 1,365.20 | 1,365.20 |
| FRT LH DOOR <i>bt</i>                        | 1   | 1,365.20 | 1,365.20 |
| REAR BUMPER PANEL PRIMED BASIS <i>repair</i> | 1   | 1,207.55 | 1,207.55 |
| HANDLE BRACKET BASE LH ?                     | 1   | 8.75     | 8.75     |
| BASE, LOCK CYLINDER LEFT ?                   | 1   | 8.75     | 8.75     |
| COVERING DOOR PRIMED LH <i>sc</i>            | 1   | 35.45    | 35.45    |
| CARRIER OUTSIDE DOOR HANDLE FRT LH <i>sc</i> | 1   | 113.25   | 113.25   |
| LH HANDLE BRACKET PRIME COATED               | 1   | 108.25   | 108.25   |
| FRT LH DOOR OUTER MOULDING <i>sc</i>         | 1   | 89.75    | 89.75    |
| FRT LH DOOR INSIDE CHANNEL SEALING <i>sc</i> | 1   | 80.75    | 80.75    |
| FRT LH DOOR COLUMN B COVER ?                 | 1   | 64.95    | 64.95    |
| FRT DOOR WEATHERSTRIP <i>sc</i>              | 1   | 157.65   | 157.65   |
| FRT LH SEALING WINDOW FRAME INTERIO ?        | 1   | 60.50    | 60.50    |
| RR LH DOOR OUTER MOULDING <i>sc</i>          | 1   | 89.75    | 89.75    |
| REAR LH DOOR INNER WERTHERSTRIP <i>sc</i>    | 1   | 80.75    | 80.75    |

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 66626  
Date Estimated : 10/07/2023  
Prepared By : Simon Koh Eng Aun

Page No. : 2 of 5

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| SKQ719R   | WBA3A16010NS37233 | 31/10/2014 | 3161A/4 | 96325   |

| DESCRIPTION                          | QTY | PRIC   | VALUE    |
|--------------------------------------|-----|--------|----------|
| LH EXTERIOR COVER WINDOW GUIDE WEB ? | 1   | 64.95  | 64.95    |
| LH B PILLAR FINISHER OUTER ?         | 1   | 64.95  | 64.95    |
| REAR DOOR WEATHERSTRIP ✓             | 1   | 157.65 | 157.65   |
| RR LH DOOR WINDOW FRAME COVER ?      | 1   | 71.45  | 71.45    |
| Total Parts :                        |     |        | 5,195.50 |

Third Party Uninsured losses / Direct Settlement

Claim No. \_\_\_\_\_

Date 13/07/23 Excess \$5

Signature \_\_\_\_\_

Authorized \_\_\_\_\_

Used Date \_\_\_\_\_ Time \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

Surveyor's Recommendation 5 days

Resy bk part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



|                |   |           |
|----------------|---|-----------|
| Labour 1       | : | 7,131.00  |
| Parts          | : | 5,195.50  |
| Labour 2       | : | 0.00      |
| Excess         | : | 0.00      |
| Total GST @ 8% | : | 986.12    |
| Grand Total    | : | 13,312.62 |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*