



ESTIMATE

DATE OF ACCIDENT : 10/07/2023
VEHICLE : SNE9282B
MAKE & MODEL : TOYOTA NOAH
INSURANCE : ALLIANZ
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	REAR BOOT <i>Defect</i>	\$ 2300 ✓
2.	REAR BOOT CHROME GARNISH <i>Defect</i>	\$ 210 ✓
3.	REAR BOOT INNER COVER <i>Defect</i>	\$ 330 ✓
4.	REAR BUMPER <i>Defect</i>	\$ 1900 ✓
5.	BRAKE LIGHT - RIGHT <i>Defect</i>	\$ 1250 ✓
6.	SIDE PAD COVER - LEFT <i>Defect</i>	\$ 350 ✓
7.	SIDE PAD COVER - RIGHT <i>Defect</i>	\$ 350 ✓
8.	REAR END PANEL <i>Defect</i>	\$ 780 x
SPECIAL NETT		
1.	REAR NUMBER PLATE & COVER <i>Defect</i>	\$ 95 x
2.	CLIPS , RIVETS & SCREWS <i>Defect</i>	\$ 100 ✓

30



JACK CARS

DRIVE WITH ASSURANCE

3.	REAR WINDSCREEN <i>Shattered</i>	\$ 2700 ✓
4.	REAR WINDSCREEN MOULDING <i>m</i>	\$ 295 ✓
5.	REAR CAMERA <i>not missing</i>	\$ 650 ✓
6.	"TOYOTA" EMBLEM <i>for</i>	\$ 95 ✓
7.	"HYBRID" EMBLEM	\$ 75 ✓
LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1500 <i>400</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 1500 <i>400</i>
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 250 <i>30</i>
4.	TO REMOVE & REINSTALL SENSORS	\$ 200 <i>50</i>
5.	TO REMOVE , CLEAN SHATTERED GLASS & INSTALL REAR WINDSCREEN	\$ 350 <i>180</i>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		PARTS + 10%: \$ 8,217
		SPECIAL NETT : \$ 4,010
		LABOUR : \$ 3,800
		TOTAL : \$ 16,027
		8% GST : \$ 1,282.16
		GRAND TOTAL : \$ 17,309.16

*Not Authorized
Excess \$2K.*

*Adrian L.
P/P 11/07/23
05 Sep*