

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 13 Jul 2023

Preliminary Advice

Vehicle No	: SNE9282B	Accident Date	: 10/07/2023
Make	: TOYOTA NOAH	Policy No.	: SP2002597171
Assignment Date	: 10/07/2023	Excess	: S\$2,000.00
Date of Inspection	: 11/07/2023	Est. Duration of Repair	: 5
Inspection At	: JACK CARS ENTERPRISE PTE LTD (HQ) B/3007 UBI ROAD 1, #01 - 450 SINGAPORE 408701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,027.00
Revised Amount	:S\$	12,264.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,264.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	102,389.00
Salvage Value	:S\$	
Margin for Repair	:S\$	82,611.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : the vehicle repair on parts by part basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.