

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLE512X/2307084

10th July 2023

The Manager
Motor Claim Department
Allianz Insurance Singapore Pte. Ltd
79 Robinson Road
#09-01
Singapore 068897

Not Authorized
LH
Express \$500
Take photo before repairing.
S. J. C.
P/P # 5195.95
2/7/23

Date of Accident : 08th July 2023
Location : MBS Carpark
Name of Policyholder : Lee Chong
Policy No : SP2002092755
Vehicle No : SLE 512 X Lexus ES250

Estimated Cost Plus/ Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front fender LH <i>011</i>	1	380.00	\$ - 380.00 ✓
2	Front fender cowling LH <i>Tri. 1</i>	1	130.00	\$ - 130.00 ✓
3	Front fender cowling clips LH <i>1ea</i>	1	15.00	\$ - 15.00 ✓
4	Headlamp assy LH <i>one</i>	1	1,500.00	\$ - 1,500.00 ✓
5	Front bumper fascia <i>Tri. 1</i>	1	370.00	\$ - 370.00 ✓ 270
6	Front bumper clips <i>1ea</i>	1set	15.00	\$ - 15.00 ✓
7	Front bumper side retainer LH <i>one</i>	1	40.00	\$ - 40.00 ✓
8	Front bumper fog lamp chrome LH <i>SL</i>	1	75.00	\$ 75.00 X
9	Front bumper fog lamp assy LH <i>11</i>	1	110.00	\$ 110.00 X
10	Front fender garnish LH <i>SL</i>	1	85.00	\$ 85.00 X
11	Front support panel <i>R</i>	1	560.00	\$ 560.00 X
12	Radiator top garnish <i>11</i>	1	140.00	\$ 140.00 X
13	Radiator top garnish clips <i>11</i>	1set	15.00	\$ 15.00 X
14	Front wheel house panel LH <i>R</i>	1	350.00	\$ 350.00 X
15	Front shock absorber LH <i>11</i>	1	350.00	\$ 350.00 X
16	Front wheel bearing <i>11</i>	1	70.00	\$ 70.00 X
17	Front knuckle arm LH <i>11</i>	1	350.00	\$ 350.00 X
18	Front wheel hub LH <i>11</i>	1	100.00	\$ 100.00 X
19	Front lower arm LH <i>11</i>	1	150.00	\$ 150.00 X
20	Front drive shaft assy LH <i>11</i>	1	2,005.20	\$ 2,005.20 X
21	Steering rack & pinion assy <i>11</i>	1	750.00	\$ 750.00 X
				\$ 7,560.20

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLE512X/2307084

10th July 2023

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 7,560.20
22	Front view mirror assy LH R	1	2,269.90	\$ 2,269.90 X
23	Front bumper side support LH M	1	180.00	\$ 180.00 X
24	Front grille M	1	520.00	\$ 520.00 X
25	Front grille chrome one side	1	130.00	\$ 130.00 X
				\$10,660.10
	Cost Plus		10%	\$ 1,066.01
				\$11,726.11
26	Front wheel rim LH (s/nett) CUY LR 500 S/M		3,502.00	\$ 3,502.00
27	Front wheel tyre LH (s/nett) SUC	1	780.00	\$ 780.00 X
				\$16,008.11

Labour Charges :-

	Amounts
Towing fee	\$ 180.00 130
Cut out, renew, knocking & welding front fender LH, front wheel house panel LH, remove & install all damage parts, straighten & re-align body	\$ 1,400.00 800
Remove & install front undercarriage to facilitate repairs	\$ 480.00 X
Computerise wheel alignment	\$ 180.00 80
Spray painting on damage parts	\$ 1,680.00 90.0
Check all lighting after repairs	\$ 80.00 20

Labour Charge	\$ 4,000.00
Total Amount	\$20,008.11

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-2514.5
102
2765-25
500
L-1930
5195-25

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLE512X/2307084

10th July 2023

The Manager
Motor Claim Department
Allianz Insurance Singapore Pte. Ltd
79 Robinson Road
#09-01
Singapore 068897

Date of Accident : 08th July 2023
Location : MBS Carpark
Name of Policyholder : Lee Chong
Policy No : SP2002092755
Vehicle No : SLE 512 X Lexus ES250

Supplementary Supply of Parts

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Side mirror lamp LH <i>scn</i>	1	65.00	\$ 65.00 ✓
2	Bonnet hinge LH <i>snf</i>	1	45.00	\$ 45.00 ✓
3	Front fender brace bracket LH <i>snf</i>	1	50.00	\$ 50.00 ✓
4	Fender trim clips <i>new</i>	1	2.50	\$ 2.50 ✓
5	Front fender seal clips <i>new</i>	1	2.00	\$ 2.00 ✓
				\$ 164.50
Cost Plus			10%	\$ 16.45
				\$ 180.95

GST will be reflected in the final bills.