

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 19 Jul 2023

Preliminary Advice

Vehicle No	: SLE512X	Accident Date	: 08/07/2023
Make	: LEXUS ES250	Policy No.	: SP2002092755
Assignment Date	: 11/07/2023	Excess	: S\$500.00
Date of Inspection	: 12/07/2023	Est. Duration of Repair	: 5
Inspection At	: SPECIALIST MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,189.06
Revised Amount	:S\$	5,195.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,195.95
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	44,534.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,466.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary.
Enclosed the latest estimate with cost price.