



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

CO. REG. No.: 1995-01140-D

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
METRO PL INTERNATIONAL PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/07/2023
Vehicle Reg. No.:	SMD4022K	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	SUBARU FORESTER, 2.0 (A)	Vehicle Reg. Date:	17/08/2018
Vehicle Colour:	BLACK		
Engine No:	FB20YE38664	Chassis No:	JF1SJ5KC5JG111717
Odometer:	60000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

Not Applicable
11/7/23
the photo taken by
3 days
p/p s

COST OF CLAIMS

	Amount
Parts	2,614.90
Miscellaneous Items	0.00
Labour	1,480.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,094.90
+ GST 8.00% (S\$)	327.59
Nett Amount (S\$)	4,422.49

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consulting Services

the Follower of the following:

- To resurvey before/after spray painting
- To assess damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurer

Acknowledged by Follower

Signature

Date

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jul 2023)

Parts: M1-SUV SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SMD4022K/08/07/2023 12:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE LOGO <i>m</i>	0.00	0.00	*60.00 F <i>✓</i>
2	1		*TAILGATE EMBLEM (SUBARU) <i>reb</i>	0.00	0.00	*65.00 F <i>✓</i>
3	1		*TAILGATE EMBLEM (AWD) <i>reb</i>	0.00	0.00	*65.00 F <i>✓</i>
4	1		*TAILGATE EMBLEM (FORRESTER) <i>reb</i>	0.00	0.00	*65.00 F <i>✓</i>
5	2		*TAILLAM,P <i>m</i>	0.00	0.00	*660.00 F <i>α</i>
6	1		*REAR BUMPER <i>DD / 70mm</i>	0.00	0.00	*400.00 F <i>✓</i>
7	2		*REAR BUMPER SIDE RETAINER <i>reb</i>	0.00	0.00	*40.00 F <i>✓</i>
8	1		*REAR BUMPER CLIPS <i>reb</i>	0	0.00	*40.00 FS <i>✓</i>
9	1		*REAR BUMPER RIVETS <i>m</i>	0	0.00	*60.00 FS <i>x</i>
10	1		*REAR BUMPER LOWER COVER <i>grend</i>	0.00	0.00	*40.00 F <i>✓</i>
11	2		*REAR BUMPER LOWER BRACKET <i>reb</i>	0.00	0.00	*44.00 F <i>✓</i>
12	1		*REVERSE SENSOR	0	0.00	*250.00 FS <i>✓</i>
13	1		*REAR BUMPER LUGGAGE SCUFF PLATE <i>grend</i>	0.00	0.00	*350.00 F <i>✓</i>
14	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*270.00 F <i>?</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,409.00
+ Margin on L,N Items 10.00% (S\$)	205.90
Total Parts (S\$)	2,614.90

Falcon-Air Auto Services Pte Ltd/SMD4022K/08/07/2023 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK REAR WIRING	New	20 50.00
2	TO FIT REVERSE SENSOR ON NEW BUMPER	New	50.00 ✓
3	TO RUSTPROOF ON ACCIDENT DAMAGE AREA	New	12 180.00 X
4	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	300 500.00
5	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	480 700.00
Gross Labour Cost (S\$)			1,480.00

Falcon-Air Auto Services Pte Ltd/SMD4022K/08/07/2023 12:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg