

Not Authorised
t/Ring 8

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD391E

AAD2307-027

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

12 JUL 2023

SHD391E
VF1ABL15AUC283416
200303878K
RENAULT
LATITUDE
9/7/2023
SMR7730G/ALLIANZ
30/9/2016

PART

LIST

1	BUMPER COVER REAR	\$	CM	561.70	—
1	BUMPER BRACKET CTR REAR	\$	SL	98.10	X
1	BUMPER BRACKET SIDE LH REAR	\$	DRY	80.80	—
1	BUMPER BRACKET SIDE RH REAR	\$	SL	82.10	X
1	BUMPER RETAINER LH REAR	\$	CM	54.20	—
1	BUMPER RETAINER RH REAR	\$	SL	59.80	X
1	BUMPER LOWER REAR	\$	CM	411.90	—
1	BUMPER BEAM REAR	\$	Ry	547.80	—
1	BUMPER BEAM BRACKET LH REAR	\$	N	114.50	X
1	BUMPER BEAM BRACKET RH REAR	\$	N	114.50	^
1	BUMPER REFLECTOR LH	\$	Rv	16.60	—
1	BOOT REFLECTOR LAMP LH	\$	SL	277.70	X
1	TAILLAMP LH	\$	CM	401.40	—
1	OUTER PANEL REAR (End Panel)	\$	N	745.80	X
1	OUTER PANEL REAR (End Panel) TRIM	\$	SL	404.56	^
1	BOOT REAR	\$	N	1,677.20	X
1	BOOT FINISHER	\$	SL	344.70	X
1	BOOT LOCK	\$	N	246.60	X
1	BOOT WEATHERSTRIP	\$	SL	178.20	X
1	BOOT STRUT LH	\$	SL	145.10	X
1	BOOT STRUT RH	\$	SL	145.10	X
1	BOOT HINGE LH	\$	N	254.20	X
1	BOOT HINGE RH	\$	N	254.20	X
1	BOOT BADGE 'RENAULT'	\$	N	82.40	—
1	BOOT BADGE	\$	N	95.80	—

Rear LH Bender 1933-20 Bar TOTAL \$ 7,394.96
25% \$ 1,848.74

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD391E

AAD2307-027

\$ 5,546.22**SPECIAL NETT****1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	shot	700.00	400.00
\$	na	65.00	—
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	60.00	X
\$	na	180.00	30.00
\$	na	150.00	40.00
\$	na na	200.00	X
\$	na	130.00	30.00

TOTAL \$ 1,680.00**TOTAL PARTS \$ 7,226.22****LABOUR**

To rust-proofing of the affected areas.

\$ 600.00 30.00

Putty and spray painting of the affected portion.

\$ 1,200.00 66.00

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 60.00

To transfer of tailgate fittings and conduct water seepage test.

\$ na 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 10.00

To reinstall rear bumper parking sensor.

\$ 170.00 6.00

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ na 170.00 X

TOTAL \$ 4,910.00

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel Nc Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD391E

AAD2307-027

OVERALL TOTAL \$ 12,136.22

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: