

ASS. REG. BY: TajREF: CS/11123007014/T93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop. m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$94K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seer: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC 3085P Yr Regn: 20/71 act

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lia Soneito c.c. 2199Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 70877 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV4PH815M4.5379872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 11/7/23Survey held at Cars & Color

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / I.E.P. (?)

CARS & COLOR PTE LTD

Automobile Parts Specialist, Professional Bodywork Restoration, Automobile Engineering Repair

SNC3085D KIA SORENTO

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 987.00 <i>de</i>
2	2	Front bumper side bracket	\$ 200.00 <i>x</i>
3	2	Front bumper right side retainer	\$ 200.00 <i>x</i>
4	1	Front lower trim cover-silver	\$ 295.00 <i>cut</i>
5	1	Front bumper lower lip grille	\$ 285.00 <i>de</i>
6	1	Front lower lip	\$ 685.00 <i>x</i>
7	1	Fog lamp cover -left	\$ 195.00 <i>x</i>
8	1	Fog lamp base -left	\$ 225.00 <i>x</i>
9	1	Tow cover	\$ 95.00 <i>x</i>
10	1	Headlight left	\$ 2,200.00 <i>x</i>
11	1	Headlight right	\$ 2,200.00 <i>cm</i>
12	1	Front light bracket right-left	\$ 220.00 <i>x</i>
13	1	Front grille assy base	\$ 600.00 <i>cut</i>
14	1	Front grille chome cover	\$ 450.00 <i>cut</i>
15	1	Front top panel cover	\$ 225.00 <i>x</i>
16	1	Front reinforcement	\$ 585.00 <i>x</i>
17	1	Reinforcement sponge	\$ 250.00 <i>cut</i>
18	2	Front sensor	\$ 300.00 <i>x</i>
19	1	Logo emblem assy-scratches	\$ 105.00 <i>ng</i>
20	1	Front light module left	\$ 985.00 <i>x</i>
21	1	Front bonnet	\$ 2,600.00 <i>bl</i>
22	1	Bonnet hinge	\$ 340.00 <i>x</i>
23	2	Bonnet absorber	\$ 400.00 <i>x</i>
24	1	Bonnet garnish rubber seal	\$ 265.00 <i>x</i>
25	1	Bonnet lock support bracket	\$ 265.00 <i>x</i>
26	1	Rear bumper	\$ 1,267.00 <i>de</i>
27	2	Rear bumper side backet	\$ 200.00 <i>cut</i>
28	1	Behind tow cover	\$ 95.00 <i>de</i>
29	2	Rear bumper side reflector	\$ <i>LH</i> 220.00 <i>RH</i> <i>cut</i>
30	2	Rear bumper side lights	\$ <i>LH</i> 380.00 <i>RH</i> <i>cut</i>
31	1	Rear reinforcement	\$ 685.00 <i>x</i>
32	1	Rear fender light-left	\$ 950.00 <i>cm</i>
33	1	Rear fender light-right	\$ 950.00 <i>x</i>
34	1	Tailgate light-light	\$ 750.00 <i>x</i>
35	1	Tailgate light-right	\$ 750.00 <i>x</i>
36	2	Logo emblem assy-KIA Sorento	\$ 180.00 <i>new</i>
37	1	Rear lower trim cover-silver	\$ 295.00 <i>dis</i>
38	1	Rear bumper lower lip grille	\$ 785.00 <i>cut</i>
39	2	Sensor	\$ 500.00 <i>ru</i> / 400
40	1	Sensor cable harness	\$ 480.00 <i>x</i>

41	1	Rear tailgate	\$	2,500.00	bt ✓
42	1	Rear tailgate rubber seal	\$	285.00	X
43	2	Rear tailgate absorber	\$	400.00	X
44	1	Rear exhaust	\$	1,300.00	bt ✓
45	2	Exhaust mounting	\$	160.00	dl ✓
		Parts Sub-total	\$	28,289.00	

CARS & COLOR PTE LTD

Automobile Parts Specialist, Professional Bodywork Restoration, Automobile Engineering Repair

SNC3085D KIA SORENTO

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips	\$ 100.00 3 Over ✓
2	10	Front bumper lower grille clips	\$ 80.00 2 Over
3	8	Front bumper lower lip clips	\$ 80.00 X
4	10	RR bumper clips	\$ 100.00 3 Over ✓
5	10	RR bumper lower grille clips	\$ 80.00 2 Over ✓
6	8	RR bumper lower lip clips	\$ 80.00 X
7	10	Front middle chrome clips	\$ 80.00 X
8	6	Front support panel top garnish clips	\$ 60.00 X
9	1	Front number plate with casing	\$ 80.00 45 Over ✓
10	1	RR number plate with casing	\$ 100.00 X
11	1	Coolant, gas necessary to facilitate	\$ 100.00 X
		Special Nett Items Total	\$ 900.00

CARS & COLOR PTE LTD

Automobile Parts Specialist, Professional Bodywork Restoration, Automobile Engineering Repair

SNC3085D KIA SORENTO

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 2,500.00 900
2	Labour putty and spray painting front and behind portion.	\$ 2,000.00 1,000
3	Labour to apply anti rust proofing to front left affected area	\$ 150.00 X
4	Labour to check wiring and focus front headlamp and wiring cable	\$ 120.00 40
5	Labour to check wiring and focus rear lights and wiring cable	\$ 120.00 40
6	Labour to remove and install rear bonnet lock mechanism	\$ 100.00 60
7	Labour to remove and install rear exhaust system	\$ 380.00 80
8	Labour to check, remove and replace aircon related radiator, high pressure and low pressure hose, check air-con, top up gas etc	\$ 250.00 X
9	Labour to remove and install rear and behind parking sensors	\$ 80.00 40
10	Labour to remove and install front and behind parking sensors	\$ 80.00 40
11	To conduct chassis alignment necessary	\$ 150.00 X
12	Remove fault code, programming	\$ 500.00 X
13	Water Test-necessary after panel beating and body work repair	\$ 120.00 X
14	To conduct necessary balance front wheel	\$ 100.00 X
15	Ceremic coating for the front and behind portion	\$ 500.00 X
16	Labour to insall reverse camera	\$ 120.00 40
Total labour :		\$ 7,270.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total labour : 7,270.00
Total repair cost : 7,270.00

Tanfkin 97495749 / 62563561
WP 12/7/23 04pm
L/S Resurvey after repair
Tanfkin @ 11hantdown.
07days