



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI23007018/Uqy3m4

Date: 26/07/2023

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 4576Y	Veh. Inspected	SMQ 5805T
Policy No.		Coverage (\$)	0.00
Claim No.	D23002406MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	11/07/2023

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MR2BE3BE100003034	Colour	SILVER
Odometer	54859 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	7 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	7 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	7 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	09/07/2023	Inspection Date	12/07/2023
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------