

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hiew, Chasin

Date: 25 Jul 2023

Preliminary Advice

Vehicle No	: SKU7618G	Accident Date	: 07/07/2023
Make	: AUDI A1	Policy No.	: 7210102873-01
Assignment Date	: 14/07/2023	Excess	: S\$600.00
Date of Inspection	: 20/07/2023	Est. Duration of Repair	: 6
Inspection At	: 281 ALEXANDRA ROAD, 159938		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,014.00
Revised Amount	:S\$	11,457.00
Check Items (Estimated)	:S\$	18,326.00
Total	:S\$	29,783.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	16,722.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,278.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : The repairer able to repair the vehicle not more than \$20,000.00.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.