

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0509/2023/EQ
DATE : 30-May-23
WIP : 22489

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/7/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MISS LEE CHIEW MUAY
ADDRESS : 90 JELICOE ROAD
SINGAPORE 208749

TELEPHONE : HP +65 96319428
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070096456-02
VEHICLE NO : **SMT 5636 Z**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 1/7/2020
ENGINE NO : CZD 893005
CHASSIS NO : WAUZZZF37L1096711
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-May-23
PLACE OF ACCIDENT : INFRONT OF 53 UBI ROAD 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 5636 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER AND BOTH REAR WHEEL ARCH TRIMS.	\$	4,000.00	
5	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 8,272.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 5636 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,839.00	
2	REAR BUMPER SPOILER	1	\$ 540.00	
3	REAR BUMPER ADAPTER - LH	1	\$ 101.00	
4	REAR BUMPER BRACKET	1	\$ 57.00	
5	REAR BUMPER GUIDE SECTION - LH	1	\$ 75.00	
6	REAR DOOR - LH	1	\$ 3,203.00	
7	REAR DOOR OUTER SEAL - LH	1	\$ 159.00	
8	REAR DOOR CATCH	1	\$ 141.00	
9	REAR SILL PANEL SEAL - LH	1	\$ 159.00	
10	REAR DOOR COVER - LH	1	\$ 389.00	
11	REAR WHEEL COVER - LH / RH	2	\$ 1,200.00	
12	REAR ALUMINIUM RIM - LH	1	\$ 1,485.00	
13	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
14	REAR WHEEL HOUSING LINER	1	\$ 283.00	
15	REAR WHEEL SPOILER - LH	1	\$ 47.00	
16	REAR SIDE MEMBER TRIM - LH	1	\$ 200.00	
17	LHS REAR TYRE	S/N	TBC	
18	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 10,382.00	
TOTAL LABOUR CHARGES		:	\$ 8,272.00	
GRAND TOTAL		:	\$ 18,654.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT