# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 17 Jul 2023

# **Preliminary Advice**

Vehicle No : SMT5636Z Accident Date : 25/05/2023 Make : AUDI Q3 SPORTBACK Policy No. : 2070096456 Assignment Date : 17/07/2023 **Excess** : S\$0.00 Date of Inspection : 14/07/2023 Est. Duration of Repair : 5

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 18,654.00 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 6,307.00  |
| Check Items (Estimated)     | :S\$ | 500.00    |
| Total                       | :S\$ | 6,807.00  |

Lump Sum Repair :S\$

# **Total Loss Consideration**

New for Old Value :S\$

 Pre-Accident Value
 :S\$
 150,000.00

 COE / PARF Rebate
 :S\$
 50,793.00

Salvage Value :S\$

Margin for Repair :S\$ 99,207.00

#### Remarks

| ( x ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have |
|-------|---|
|       | your authorisation.   |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.