Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 (Claims & Performance

Management) Singapore 068897 From: LKK Auto Consultants Pte Ltd

> 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

> > : 5

Attn: JANICE KOH Date: 18 Jul 2023

Preliminary Advice

Vehicle No : SJD7461S Accident Date : 08/07/2023

Make : TOYOTA WISH Policy No. : SP2005237661-01

Assignment Date : 12/07/2023 **Excess** : S\$600.00 Date of Inspection : 13/07/2023 Est. Duration of Repair

Inspection At : FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)

BLK 9006 #01-200 TAMPINES ST 93

SINGAPORE

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,469.50
Revised Amount	:S\$	6,790.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,790.00
	0.0	F 400 00

Lump Sum Repair :S\$ 5,400.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 48,000.00 COE / PARF Rebate :S\$ 21,216.00

Salvage Value :S\$

Margin for Repair :S\$ 26,784.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :