



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2005237661-01	Date of Loss:	08/07/2023
Vehicle Reg. No.:	SJD7461S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOH BOON CHUAN GABRIEL	Contact No:	+6592988168
Driver:	KOH BOON CHUAN GABRIEL		

Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	01/04/2008
Vehicle Colour:	SILVER		
Engine No:	1ZZ3078534	Chassis No:	ZNE100404338
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **6**

not Accident
1/59
5 days
express? Temp. pl. After 13/7/23

Present Location: **FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)**

COST OF CLAIMS	Amount
Parts	6,869.50
Miscellaneous Items	0.00
Labour	2,600.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,469.50
+ GST 8.00% (S\$)	757.56
Nett Amount (S\$)	10,227.06

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2023)
Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SJD7461S/12/07/2023 12:29
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>D2/34C</i>	0.00	0.00	*510.00 F ✓
2	2		*BONNET HINGES <i>R</i>	0.00	0.00	*120.00 F X
3	1		*BONNET LOGO <i>Abba n1</i>	0.00	0.00	*60.00 F X
4	1		*BONNET CHROME MOULDING <i>CN</i>	0.00	0.00	*190.00 F ✓
5	1		*BONNET INSULATOR <i>11</i>	0.00	0.00	*190.00 F X
6	10		*BONNET INSULATOR CLIPS <i>ner</i>	0.00	0.00	*40.00 F ✓
7	1		*BONNET LOCK <i>Tw1</i>	0.00	0.00	*90.00 F ✓
8	1		*BONNET RUBBER SEAL <i>ner</i>	0.00	0.00	*30.00 F ✓
9	1		*FRONT BUMPER <i>To-1</i>	0.00	0.00	*480.00 F ✓
10	2		*FRONT BUMPER SIDE RETAINER <i>Surf/ner</i>	0.00	0.00	*120.00 F ✓
11	1		*RADIATOR GRILLE <i>To-1</i>	0.00	0.00	*140.00 F ✓
12	2		*RADIATOR GRILLE STOPPER CLIPS <i>ner</i>	0.00	0.00	*40.00 F ✓
13	1		*FRONT NUMBER PLATE <i>Surf</i>	0.00	0.00	*45.00 F 40
14	1		*FRONT BUMPER SPONGE <i>NF</i>	0.00	0.00	*110.00 F X
15	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*240.00 F ?
16	2		*HEADLAMP	0.00	0.00	*1,560.00 F ?
17	1		*BRACE PANEL <i>Tw1</i>	0.00	0.00	*120.00 F ✓
18	1		*FRONT SUPPORT PANEL <i>Surf/ner</i>	0.00	0.00	*600.00 F ✓
19	1		*AIR-CON CONDENSER	0.00	0.00	*750.00 F ?
20	1		*RADIATOR	0.00	0.00	*770.00 F ?
21	1		*COOLANT	0.00	0.00	*40.00 F ?

F=Franchise part.

Sub Total (S\$)	6,245.00
+ Margin on L,N Items 10.00% (S\$)	624.50
Total Parts (S\$)	6,869.50

Falcon-Air Auto Services Pte Ltd/SJD7461S/12/07/2023 12:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING AND FOCUS HEADLAMP	New	20 50.00
2	TO VACCUM,RE-OIL AND RENEW AIR-CON GAS	New	100 150.00
3	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR INNER PANEL, REWELD INNER PANEL,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	600 1,000.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	600 1,400.00
Gross Labour Cost (\$\$)			2,600.00

Falcon-Air Auto Services Pte Ltd/SJD7461S/12/07/2023 12:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg