



**Section A - Accident Details**

Registration Number	SHB1233H
Case Reference Number	TAX/07/23/2024
Registration Date	26/Dec/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TEO SENG YEONG
Type of Accident	Head to Rear
Accident Date and Time	11/Jul/2023 7:45 AM
Accident Reported Date and Time	11/Jul/2023 10:42 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118839
Special Instruction to ARC, if any	TP/ REAR RIGHT PORTION
Prepared Date and Time	11/Jul/2023 2:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$818.00	\$200.00
Total Spare Part Cost	\$2,700.79	\$791.70
Total Other Cost	\$796.88	\$8.30
<b>TOTAL COST</b>	<b>\$4,991.67</b>	<b>\$1,200.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Taufikh (LKK) / INCOME</b>
ARC / Surveyor Sign Off Date	<b>12/07/2023 2:33 PM</b>	<b>12/07/2023 11:11 AM</b>
Signature		
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Taufikh (LKK) / HP : 9749 5749 / Email : taufikh@lkkauto.com	

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2307-0258	<b>Invoice Number</b>	
<b>Quotation Date</b>	25.07.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION RH	\$676.00	\$200.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$220.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$818.00</b>	<b>\$200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Lump Sum Adjustment by Surveyor	\$0.00	(\$318.58)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$796.88</b>	<b>\$8.30</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check
		52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given
		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$143.60	0.00	\$0.00	Replace	Not Given
		52591-47080	SEAL, RR BUMPER , RH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace
		52169-47070	COVER, GUARD RR BUMPER LOWER	0.00	\$23.90	0.00	\$0.00	Replace	Not Given
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Check

X nn  
√ nec  
√ nec  
√ nec  
X nn  
X nn  
X nn  
√ nec  
√ de  
X nn  
X nn

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/07/2023

User ID : PohSuan

		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X nn
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X nn
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given	X nn
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X nn
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X nn
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X nn
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X nn
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace	Replace	√ nec
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace	√ de
<b>Total</b>					<b>\$3,368.80</b>		<b>\$791.70</b>			

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	791.70	
+	200.00	
+	526.88	L/S \$1,200/-
	1,518.58	
	-20%	
	1,214.86	