

43

SMRT Accident Vehicle Repair Estimates

FAX Number

Estimator Tel

Accident Rep

Date Generated

User ID

SHB 989

SHB 6177

Section A - Accident Details

Registration Number	SHB1233H
Case Reference Number	TAX/07/23/2024
Registration Date	26/12/19
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TEO SENG YEONG
Type of Accident	Head to Rear
Accident Date and Time	11/7/23 7:45 AM
Accident Reported Date and Time	11/7/23 10:42 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118839
Special Instruction to ARC, if any	TP/ REAR RIGHT PORTION
Prepared Date and Time	11/7/23 2:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$818.00	\$0.00
Total Spare Part Cost	\$1,736.37	\$0.00
Total Other Cost	\$796.88	\$0.00
TOTAL COST	\$4,027.25	\$0.00
Lump Sum Total	\$4,050.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	11/07/2023 2:13 PM	
Signature		
Remarks		

Tanfhi
97975749
WP' 12/7/23
@ 6045
3 days
i/s Resurvey after
repair
Tanfhi @ Watson

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

FAX Number

Estimator Tel

Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicabl
TO REPAIR REAR PORTION RH	\$676.00	200
Total Labour	\$676.00	

Part 2 - Spray Painting & Panel Beating Related Works

200

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO RESPRAY BUMPER BEAM	\$220.00	X nn
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR PANEL	\$220.00	X nn
Total Spray Painting & Panel Beating	\$818.00	200

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicabl
TO WASH AND VACUUM	\$60.00	X nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X nn
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	X nn
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	30
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88	nn /
TO REPLACE SUNDRY PARTS	\$100.00	X nn
Total Other Costs	\$796.88	326.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52023-47030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace X? Xnn	
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace de	
		52462-47130	PAD, RR BUMPER, RH & LH, 3	2.00	\$12.00	25.00	\$18.00	Replace ne	
		52462-47030	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace ne	
		52462-47020	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace ne	
		52461-47070	PAD, RR BUMPER, CTR	3.00	\$12.00	25.00	\$27.00	Replace ne	
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace nnX	
		52599-68030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace nnX	
		52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	25.00	\$107.70	Replace nnX	
		52591-47080	SEAL, RR BUMPER, RH	1.00	\$128.00	25.00	\$96.00	Replace nnX	
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace ne	
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace de	
		52169-47070	COVER, GUARD RR BUMPER LOWER	1.00	\$23.90	25.00	\$17.92	Replace X nn	
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1.00	\$42.20	25.00	\$31.65	Replace ?Xnn	
		58398-47050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace X nn	
		66259-47010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace X nn	
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1.00	\$282.70	10.00	\$254.43	Replace X nn	

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace <input checked="" type="checkbox"/> nn	
		89997-30100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	10.00	\$70.20	Replace <input checked="" type="checkbox"/> nn	
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace <input checked="" type="checkbox"/> nn	
Total					\$3,368.80		\$2,700.79		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
otal									

1055.40
25%-791.55

200
200
326.88
791.55
1518.43
l/s\$1200
3 days



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/07/2023 14:46 (SGT)
Reported by	Actual Driver
Date of Accident	11/07/2023 07:45 (SGT)
Exact Location of Accident	Seletar North Link, Singapore
Additional Location Information	SELETAR NORTH LINK TOWARDS ST AEROSPACE ENGINEERING
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB1233H

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-6866267
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-23100854MFSH

DRIVER

Name of Driver	TEO SENG YEONG
NRIC No	SXXXX490C
Date Of Birth	07/09/1963