



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SBS 8399Z

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRONT WINDSCREEN N	SHATTERED	760.00
6	ADHESIVE SIKA 265 600ML SAUSAGE N	NECESSARY	78.00
			838.00
	<u>LABOUR</u>		
	WORKSHOP LABOUR.		188.00
	CONTRACTOR'S REPAIR CHARGES.		750.00
			938.00
GRAND TOTAL			1,776.00

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)	1,776.00
---	-----------------

Report Ref No. CS/LPC23007065/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.