

4

Kenneth

2724

The U/C / Chassis frame / Body Structure affected due to collision.

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-02 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee_vehicle@yahoo.com.sg

GST Registration No: M90374725J

Kennerh CLKK)

96910663

Our Ref No. : SB-20837

Date: 11-Jul-23

Kennerh Hong @ lkk auto.com

AMK Workshop.

Foreman: Li Ming

FAX: 64562752

QUOTATION FOR ACCIDENT REPAIR ON BUS NO:

SBS8399Z

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

1)	Vehicle No : Model :	SBS8399Z SD												
2)	Total Cost :	<table><tr><td>- Material & Parts Cost</td><td>:</td><td></td></tr><tr><td>- Labour Cost</td><td>:</td><td>\$ 750.00</td></tr><tr><td>GST (8%) :</td><td>\$</td><td>60.00</td></tr><tr><td>Total :</td><td>\$</td><td>810.00</td></tr></table>	- Material & Parts Cost	:		- Labour Cost	:	\$ 750.00	GST (8%) :	\$	60.00	Total :	\$	810.00
- Material & Parts Cost	:													
- Labour Cost	:	\$ 750.00												
GST (8%) :	\$	60.00												
Total :	\$	810.00												
		Work Scopes Dismantle and replace front windscreen Repair of dome Repair of driver side body panel Touch up putty and respray  Supply workers for 19 ManHour TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included (B) Materials and Parts: - Supply by SBS Transit C) Mechanical/Engine Effect - NA												

Note: Quotation valid for 1 Month only

This is a computer-generated document. No signature will be required.

97961189

Li Ming