

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0650/2023/EQ
DATE : 12-Jul-23
WIP : 28739

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/7/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS KLARA THAMRIN
ADDRESS : 8 RODYK ST
#09-01
SINGAPORE 238216
TELEPHONE : HP +65 96600588
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220093248
VEHICLE NO : **SNK 2310 T**
MODEL CODE : AUDI Q3 SPORTBACK 2.0 TFS
MODEL YEAR : 15/8/2022
ENGINE NO : DNN 094508
CHASSIS NO : WAUZZZF30N1143645
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Jul-23
PLACE OF ACCIDENT : PARALLEL PARK AT MOHAMAD SULTAN

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 2310 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT CAMERA ASSY.	S/N \$ 380.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO REMOVE AND RENEW FRONT BUMPER ASSY AND RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
4	TO DISMANTLE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00	
5	TO RESPRAY FRONT BUMPER, LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER, AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,300.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 7,952.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 2310 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,508.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 458.00	
3	FRONT BUMPER CONNECTING PIECE	1	\$ 171.00	
4	FRONT BUMPER TRIM - LOWER	1	\$ 421.00	
5	FRONT BUMPER GRILLE - CENTER	1	\$ 256.00	
6	FRONT BUMPER SPOILER	1	\$ 900.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 181.00	
8	FRONT BUMPER TRIM - RH	1	\$ 193.00	
9	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 31.00	
10	RADIATOR GRILLE	1	\$ 2,262.00	
11	RADIATOR GRILLE COVER	1	\$ 288.00	
12	RADIATOR GRILLE STRIKER PLATE	1	\$ 288.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 121.00	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,030.00	
15	FRONT BUMPER GUIDE SECTION - RH	1	\$ 46.00	
16	FRONT PARKING AID SENSOR - RH	1	\$ 265.00	
17	FRONT PARKING AID SEAL RING	4	\$ 11.00	
18	FRONT FENDER - RH	1	\$ 1,530.00	
19	FRONT FENDER ATTACHMENT PARTS	1	\$ 69.00	
20	FRONT FENDER BRACE - RH	1	\$ 104.00	
SUB TOTAL SPARE PARTS		:	\$ 10,133.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 2310 T**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - RH	1	\$ 281.00	
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
23	FRONT WHEEL COVER - LH / RH	2	\$ 1,200.00	
24	HEADLIGHT - RH	1	\$ 6,305.00	
25	HEADLIGHT POWER MODULE	1	\$ 876.00	
26	HEADLIGHT HEAT SINK	1	\$ 924.00	
27	HEADLIGHT MOUNTING - RH	1	\$ 140.00	
28	FRONT DOOR COVER - RH	1	\$ 413.00	
29	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 20,677.00	
TOTAL LABOUR CHARGES		:	\$ 7,952.00	
GRAND TOTAL		:	\$ 28,629.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT