

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0650/2023/EQ  
**DATE** : 12-Jul-23  
**WIP** : 28739

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/7/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS KLARA THAMRIN  
**ADDRESS** : 8 RODYK ST  
#09-01  
SINGAPORE 238216  
**TELEPHONE** : HP +65 96600588  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220093248  
**VEHICLE NO** : SNK 2310 T  
**MODEL CODE** : AUDI Q3 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 15/8/2022  
**ENGINE NO** : DNN 094508  
**CHASSIS NO** : WAUZZZF30N1143645  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Jul-23  
**PLACE OF ACCIDENT** : PARALLEL PARK AT MOHAMAD SULTAN

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 2310 T**

| S/N                         | NATURE OF JOBS                                                                                                                                   |        | ESTIMATED CHARGES  | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT CAMERA ASSY. | S/N \$ | 380.00             | /                          |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.                                                                              | S/N \$ | 400.00             | /                          |
| 3                           | TO REMOVE AND RENEW FRONT BUMPER ASSY AND RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                | \$     | 2,400.00           | 1000                       |
| 4                           | TO DISMANTLE AND REINSTALL RHS WING MIRROR ASSY.                                                                                                 | S/N \$ | 280.00             | /                          |
| 5                           | TO RESPRAY FRONT BUMPER, LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER, AND BOTH FRONT WHEEL ARCH TRIMS.                           | \$     | 4,300.00           | 2600                       |
|                             |                                                                                                                                                  |        |                    | 550 x 4 + 400              |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                   | S/N \$ | 192.00             | /                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | :      | <b>\$ 7,952.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 2310 T**

|                              |                                               |     | DAMAGED PARTS & PRICES |                  |
|------------------------------|-----------------------------------------------|-----|------------------------|------------------|
| S/N                          | PARTS DESCRIPTION                             | QTY | S/NETT                 | REMARKS          |
| 1                            | FRONT BUMPER <i>de</i>                        | 1   | \$                     | 1,508.00         |
| 2                            | FRONT BUMPER FIXING PARTS ?                   | 1   | \$                     | 458.00           |
| 3                            | FRONT BUMPER CONNECTING PIECE ?               | 1   | \$                     | 171.00           |
| 4                            | FRONT BUMPER TRIM - LOWER ?                   | 1   | \$                     | 421.00           |
| 5                            | FRONT BUMPER GRILLE - CENTER X                | 1   | \$                     | 256.00           |
| 6                            | FRONT BUMPER SPOILER <i>de</i>                | 1   | \$                     | 900.00           |
| 7                            | FRONT BUMPER AIR GUIDE GRILLE - RH <i>3er</i> | 1   | \$                     | 181.00           |
| 8                            | FRONT BUMPER TRIM - RH ?                      | 1   | \$                     | 193.00           |
| 9                            | FRONT PARKING AID SENSOR SUPPORT - RH ?       | 1   | \$                     | 31.00            |
| 10                           | RADIATOR GRILLE X                             | 1   | \$                     | 2,262.00         |
| 11                           | RADIATOR GRILLE COVER X                       | 1   | \$                     | 288.00           |
| 12                           | RADIATOR GRILLE STRIKER PLATE X ?             | 1   | \$                     | 288.00           |
| 13                           | FRONT BUMPER FOAM FILLER PIECE                | 1   | \$                     | 121.00           |
| 14                           | FRONT BUMPER REINFORCEMENT BEAM ?             | 1   | \$                     | 1,030.00         |
| 15                           | FRONT BUMPER GUIDE SECTION - RH ?             | 1   | \$                     | 46.00            |
| 16                           | FRONT PARKING AID SENSOR - RH ?               | 1   | \$                     | 265.00           |
| 17                           | FRONT PARKING AID SEAL RING <i>m</i>          | 4   | \$                     | 11.00            |
| 18                           | FRONT FENDER - RH <i>yl</i>                   | 1   | \$                     | 1,530.00         |
| 19                           | FRONT FENDER ATTACHMENT PARTS ?               | 1   | \$                     | 69.00            |
| 20                           | FRONT FENDER BRACE - RH ?                     | 1   | \$                     | 104.00           |
| <b>SUB TOTAL SPARE PARTS</b> |                                               | :   | <b>\$</b>              | <b>10,133.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT

55, UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 2310 T**

|                             |                                              |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|----------------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                            | QTY | S/NETT                 | REMARKS |
| 21                          | FRONT WHEEL HOUSING LINER - RH ?             | 1   | \$ 281.00              |         |
| 22                          | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ? | 1   | \$ 105.00              |         |
| 23                          | FRONT WHEEL COVER - LH / RH <i>no</i> ✓      | 2   | \$ 1,200.00            |         |
| 24                          | HEADLIGHT - RH <i>no</i> ✓                   | 1   | \$ 6,305.00            |         |
| 25                          | HEADLIGHT POWER MODULE ?                     | 1   | \$ 876.00              |         |
| 26                          | HEADLIGHT HEAT SINK ?                        | 1   | \$ 924.00              |         |
| 27                          | HEADLIGHT MOUNTING - RH ?                    | 1   | \$ 140.00              |         |
| 28                          | FRONT DOOR COVER - RH <i>X</i>               | 1   | \$ 413.00              |         |
| 29                          | SUNDRIES ?                                   |     | \$ 300.00              |         |
| <b>TOTAL SPARE PARTS</b>    |                                              | :   | <b>\$ 20,677.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                              | :   | <b>\$ 7,952.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                              | :   | <b>\$ 28,629.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Plasma - 4p 90010068*  
 : *13/07/23*  
 : *6 days*  
 : *EXCESS: TBA*  
 : *Revert*  
 : *Resn 34 part*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT