

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC23007069/Tqy3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	04/08/2023	
	ATTN: EILEEN LE	E		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YN 4170X	Veh. Inspected		SJT 786S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1231239-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		12/07/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLC200	c.c		1991	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDC2539422F634719	Colour		WHITE	
	Odometer	68626 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/60R18	HABILEAD		6 mm	
	L/H Front Tyre	235/60R18	HABILEAD		6 mm	
	R/H Rear Tyre	235/60R18	HABILEAD		6 mm	
	L/H Rear Tyre	235/60R18	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.					
5.		General Information				
	Accident Date	07/07/2023	Inspect Date / T	ime	12/07/2023 (03:35 PM)	
	Survey held at	AP AUTOMOTIVE SERVICES F	<u> </u>		,	
	,	9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				