



AP AUTOMOTIVE SERVICES PTE LTD
 ROC / GST REG NO : 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date 12/7/2023
 Vehicle SJT 786S
 Make/Model MERCEDES BENZ GLC200
 Chassis No. WDC2539422F634719

No.	Description	Unit	Unit Price	Amount	
	Parts Replacment				
1	FRONT FENDER LH	1	\$ 1,898.00	\$ <i>bt</i> 1,898.00	942.01
2	FRONT FENDER COWLING LH	1	\$ 326.00	\$ nn <i>X</i> 326.00	
3	FRONT FENDER ARCED GARNISH LH	1	\$ 298.00	\$ <i>aut</i> 398.00	260
4	BONNET	1	\$ 2,556.50	\$ <i>bt</i> 2,556.50	1840
5	BONNET LOGO	2	\$ 115.00	\$ <i>nn</i> 115.00	
6	BONNET HINGE	2	\$ 156.00	\$ <i>Ry</i> 312.00	
7	HEADLAMP LH	1	\$ 3,025.00	\$ <i>cra</i> <i>✓</i> 3,025.00	
8	FRONT BUMPER	1	\$ 1,545.00	\$ <i>Ry</i> 1,545.00	
9	FRONT DOOR LH	1	\$ 2,985.00	\$ <i>dd</i> 2,985.00	
10	FRONT DOOR LOCK	1	\$ 365.41	\$ nn <i>X</i> 365.41	
11	FRONT DOOR INSULATION	1	\$ 85.40	\$ nn <i>X</i> 85.40	
12	FRONT DOOR WEATHERSTRIP LH	1	\$ 351.87	\$ xnn <i>?</i> 351.87	
13	FRONT DOOR WINDOOR LIFTER	1	\$ 813.42	\$ nn <i>X</i> 813.42	
14	FRONT DOOR WINDOW GUIDE RAIL	1	\$ 144.90	\$ nn <i>X</i> 144.90	
15	FRONT DOOR TRIM BOARD LH	1	\$ 2,459.57	\$ nn <i>X</i> 2,459.57	
16	FRONT DOOR CHROME MOULDING LH	1	\$ 98.00	\$ nn <i>X</i> 98.00	
17	FRONT DOOR HINGE LH	2	\$ 183.00	\$ nn <i>X</i> 366.00	
18	FRONT DOOR SIDE MIRROR LH	1	\$ 2,741.00	\$ <i>dis</i> 2,741.00	1350
19	FRONT WINDSCREEN MOULDING LH	1	\$ 338.00	\$ <i>cra</i> 338.00	
20	REAR DOOR LH	1	\$ 3,140.37	\$ <i>Ry</i> 3,140.37	
21	REAR DOOR WEATHERSTRIP LH	1	\$ 351.87	\$ nn <i>X</i> 351.87	
22	REAR DOOR INSULATION LH	1	\$ 85.40	\$ nn <i>X</i> 85.40	
23	REAR DOOR TRIM BOARD LH	1	\$ 2,459.57	\$ nn <i>X</i> 2,459.57	
24	REAR DOOR CHROME MOULDING LH	1	\$ 98.00	\$ nn <i>X</i> 98.00	
				\$ 27,059.28	
			Less 5%	\$ 10855.01	1,352.96
			Total	\$ 10%-9769.50	25,706.32

S/Nett Items					
1	FRONT BUMPER CLIPS	1	\$ 80.00	\$ <i>30</i> <i>X</i> nn 80.00	
2	FRONT FENDER INNER TRIM CLIP	1	\$ 80.00	\$ <i>X</i> nn 80.00	
3	FRONT DOOR BOARD CLIPS	1	\$ 100.00	\$ <i>30</i> <i>nn</i> 100.00	
4	REAR DOOR BOARD CLIPS	1	\$ 100.00	\$ nn <i>X</i> 100.00	
5	FRONT WHEEL RIM LH	1	\$ 1,200.00	\$ <i>aut</i> <i>750</i> 1,200.00	
6	FRONT TYRE LH	1	\$ 400.00	\$ <i>X</i> nn 400.00	
			Total	\$	1,960.00

	LABOUR				
1	SPRAY PAINT ON AFFECTED AREAS	1	\$ 2,000.00	\$ 1350	2,000.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1000	1,800.00
3	TO CHECK WIRING AND HEADLAMP FUNCTION	1	\$ 180.00	\$ 30	180.00
4	TO CHECK WATER LEAK	1	\$ 80.00	\$ X nn	80.00
5	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	\$ 280.00	\$ 150 ? xnn	280.00
6	TO CHECK 4 WHEEL ALIGNMENT	1	\$ 350.00	\$ 80	350.00
7	TRANSFER FRONT DOOR & REAR DOOR MECHANISM	1	\$ 300.00	\$ 60	300.00
8	TO PERFORM RUST PROOFING	1	\$ 250.00	\$ 40	250.00
			Total	\$	5,240.00
					2560

Parts Replacement Amount	\$	27,666.32
Total Amount For Labour	\$	5,240.00
Total Amount	\$	32,906.32

9769.50
780
2560
13109.50
l/s\$10,450
7 days #

Tanfiri 97495749

WP' 12/7/23 @ 340

U/S Resurvey after repair

Tanfiri @ 1/khantowin.

07days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: