

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI23007071/UQY3E2**Date:** 27/07/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLA4766A**Insured Vehicle No :** GBD3006U

Date of Loss: 10/07/2023

Nature of Claim:

TP

Claim No: CDMCG23001701

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLA4766A**

Make &amp; Model: HYUNDAI TL TUCSON, 2.0 GLS AT 2WD SR (EPB) (A)

Engine No: G4NAGU157733

Reg. Date: 02/03/2016 (Man. Year: 2016)

Chassis No: KMHJ3813MGU184446

Colour: Red

Odometer: 217144 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size:

225/60 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,368.40	4,232.80	135.60	3.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,170.00	730.00	38.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,268.40</b>	<b>5,402.80</b>	<b>865.60</b>	<b>13.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,268.40</b>	<b>4,300.00</b>	<b>1,968.40</b>	<b>31.40</b>

INSPECTION

Date of Assignment: 12/07/2023

Date Inspected: 18/07/2023

Inspected At:

Siang Hui Motor Works (HQ)  
3006 Ubi Road 1, #01-338  
Singapore 408700

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2023)
<b>Parts:</b>	M1-SUV	HYUNDAI TL TUCSON 2.0 GLS AT 2WD SR (EPB) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA4766A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,629.00 FL	*1,629.00 FL
2	1		*REAR TAILGATE OUTER GARNISH	Cracked	220.00 FL	*220.00 FL
3	1		*TUCSON LOGO	Necessary	42.00 FL	*42.00 FL
4	1		*HYUNDAI LOGO	Necessary	38.00 FL	*38.00 FL
5	1		*REAR TAILGATE OUTER GARNISH BRACKET	Cracked	183.00 FL	*183.00 FL
6	1		*REAR TAILGATE LAMP N/S	Cracked	725.00 FL	*725.00 FL
7	1		*TAIL LAMP N/S	Cracked	898.00 FL	*898.00 FL
8	1		*REAR BUMPER	Dented / Deformed	458.00 FL	*458.00 FL
9	1		*REAR BUMPER LOWER GARNISH	Grazed	366.00 FL	*366.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	280.00 FL	*280.00 FL
11	1		*REAR BUMPER LAMP N/S	Cracked	152.00 FL	*152.00 FL
12	1		*END PANEL	Repair	157.00 FL	*- FL
13	1		*REAR W/SCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
14	1		*SET REVERSE SENSOR	Malfunction	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,398.00</b>	<b>5,231.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,029.60	998.20
<b>Total Parts (\$\$)</b>	<b>4,368.40</b>	<b>4,232.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT REAR W/SCREEN	New	120.00	120.00
2	TO SPRAY PAINTING	New	880.00	600.00
3	TO REMOVE, REPLACE REAR BOOT & REAR BUMPER	New	900.00	450.00
<b>Gross Labour Cost (\$)</b>			<b>1,900.00</b>	<b>1,170.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >