

Not Notified  
1/1/2023

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SMM4030P**

**LAD2307-006**

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SMM4030P

JTDKB3FU603083530

201603575K

TOYOTA

PRIUS

3/7/2023

SMV9660R/ China.

27/6/2019

10 JUL 2023

**PART**

**LIST**

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	1	558.39	X
\$	1	19.43	X
\$	1	726.92	X
\$	1	111.41	X
\$	1	111.41	X
\$	1	155.72	X
\$	1	147.11	X
\$	1	148.58	X
\$	1	419.90	X
\$	1	220.50	X
\$	1	304.92	X
\$	1	290.43	X
\$	1	159.39	X
\$	1	824.46	X

TOTAL \$ 4,198.53

25% \$ 1,049.63

\$ 3,148.90

**SPECIAL NETT**

**1SET PARKING AID**

- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	1	700.00	X
\$	1	65.00	X
\$	1	60.00	X
\$	1	180.00	X
\$	2	150.00	X
\$	1	200.00	X
\$	1	130.00	X

TOTAL \$ 1,485.00

TOTAL PARTS \$ 4,633.90

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SMM4030P****LAD2307-006****LABOUR**

To rust-proofing of the affected areas.	\$	nn	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501

**TOTAL \$ 4,690.00****OVERALL TOTAL \$ 9,323.90***2 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: