

*Not Notified*  
*1/18/8*  
*Recovery After Paint*  
*4-5 days*

VEHICLE NO: SLG2913Z  
 CHASSIS NO: GK8-1006620

MODEL: HONDA SHUTTLE

| DESCRIPTION                      | REPAIRER'S ESTIMATE(S\$)                |
|----------------------------------|-----------------------------------------|
| <b><u>PARTS (LIST ITEMS)</u></b> |                                         |
| REAR BUMPER                      | <i>RM</i> \$ 1,210.00 ✓                 |
| REAR BUMPER RETAINER LHS         | \$ <i>RM</i> 50.00 X                    |
| REAR BUMPER RETAINER RHS         | \$ <i>RM</i> 50.00 X                    |
| REAR BUMPER REFLECTOR LHS        | \$ <i>RM</i> 70.00 X                    |
| REAR BUMPER REFLECTOR RHS        | \$ <i>RM</i> 70.00 X                    |
| REAR BUMPER REFLECTOR COVER LHS  | \$ <i>RM</i> 50.00 X                    |
| REAR BUMPER REFLECTOR COVER RHS  | \$ <i>RM</i> 50.00 X                    |
| REAR BUMPER TOWING COVER         | \$ <i>RM</i> 40.00 X                    |
| TAILGATE                         | <i>RM</i> \$ 1,200.00 ✓                 |
| TAILGATE LAMP LHS                | \$ <i>RM</i> 400.00 X                   |
| TAILGATE LAMP RHS                | \$ <i>RM</i> 400.00 X                   |
| TAILGATE WEATHERSTRIP            | <i>Notified</i> \$ 120.00 <i>50% in</i> |
| TAILGATE LOCK ASSY               | \$ <i>Not</i> 180.00 ✓                  |
| TAILGATE INNER TRIM              | \$ 210.00 7                             |
| TAIL GATE CENTRE GARNISH         | \$ <i>RM</i> 480.00 X                   |
| TAILGATE POCKET GARNISH          | \$ <i>RM</i> 80.00 X                    |
| HONDA EMBLEM                     | \$ <i>RM</i> 50.00 ✓                    |
| SHUTTLE EMBLEM                   | \$ <i>RM</i> 60.00 ✓                    |
| REAR WINDSCREEN MOULDING         | \$ <i>RM</i> 100.00 ✓                   |
| END PANEL                        | \$ 460.00 7                             |
| END PANEL TOP GARNISH            | \$ 110.00 7                             |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|                                  |  |                    |       |                 |   |
|----------------------------------|--|--------------------|-------|-----------------|---|
| SPARE TYRE PANEL                 |  |                    | \$ 11 | 990.00          | X |
| SPARE TYRE TOP COVER             |  |                    | \$ 12 | 460.00          | X |
| SPARE TYRE TOOL BOX SPONGE       |  |                    | \$ 12 | 100.00          | X |
| SPARE TYRE TOOL BOX              |  |                    | \$ 12 | 300.00          | X |
| REAR FENDER INNER TRIM LHS       |  |                    | \$    | 700.00          | 7 |
| REAR FENDER INNER TRIM RHS       |  |                    | \$ 12 | 700.00          | X |
|                                  |  |                    |       |                 |   |
|                                  |  | 20%                | \$    | 8,690.00        |   |
|                                  |  |                    | \$    | 1,738.00        |   |
|                                  |  |                    | \$    | 6,952.00        |   |
| <b><u>SPECIAL NETT ITEMS</u></b> |  |                    |       |                 |   |
| REAR SENSORS                     |  |                    | \$ 11 | 200.00          | ✓ |
| REAR BUMPER CLIPS 1 SET          |  |                    | \$ 12 | 60.00           | ✓ |
| WINDSCREEN SEALANT               |  |                    | \$ 12 | 40.00           | ✓ |
|                                  |  |                    |       |                 |   |
|                                  |  | Total              | \$    | 300.00          |   |
|                                  |  |                    |       |                 |   |
|                                  |  | <b>TOTAL PARTS</b> | \$    | <b>7,252.00</b> |   |

| S/N | DESCRIPTION                                                                                           | REPAIRER'S<br>ESTIMATE (S\$) |     |
|-----|-------------------------------------------------------------------------------------------------------|------------------------------|-----|
|     | <b><u>LABOUR</u></b>                                                                                  |                              |     |
| 1   | To remove the affected parts & fittings to commence repairs; replace damaged parts and components     | \$ 1,800.00                  | 7   |
| 2   | To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired       | \$ 1,800.00                  | 600 |
| 3   | To remove and re-fix wiring and check all electrical components at damaged areas for proper functions | \$ 100.00                    | 20  |
| 4   | To provide anti-rust treatment on affected areas                                                      | \$ 100.00                    | 30  |
| 5   | Remove and refit rear windscreen                                                                      | \$ 150.00                    | 120 |
| 6   | Transfer tailgate parts                                                                               | \$ 150.00                    | 60  |
| 7   | Remove & refit rear sensors                                                                           | \$ 80.00                     | 50  |
| 8   | Remove & refit rear upholstery                                                                        | \$ 250.00                    | 7   |
|     | Labour Total :                                                                                        | \$ 4,430.00                  |     |
|     | <b>TOTAL (PARTS &amp; LABOUR):</b>                                                                    | <b>\$ 11,682.00</b>          |     |