



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22011722/Dny3e2-1	
			Date: 14/07/2023	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6235U	Veh. Inspected	PC 5801S	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026596	Excess (\$)	0.00	
Assign From	CHARMAINE KONG	Assign Date	12/07/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE 3.0 DX	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010180584	Colour	WHITE	
Odometer	169487 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	TOYO	5 mm	
L/H Front Tyre	195 R15C	TOYO	5 mm	
R/H Rear Tyre	195 R15C	TOYO	6 mm	
L/H Rear Tyre	195 R15C	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	23/11/2022	
Survey held at	HUI WANG ENTERPRISE BLK 5 DEFU LANE 10 #01-576 . SINGAPORE 539187			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	