

李 汽 车 贸 易

GST REG NO 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

Not Authorized
LML
Tel: 62863561
maybe TOTAL LOSS
13/7/23

ESTIMATE COST OF REPAIR

Date: 12-Jul-23

Estimate no. 1291

Plate No. FBP6811D

Model. LAMBREDDIA

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 950.00	✓	
2	FORK T-UNDER BRACKET	\$ 650.00	✓	
3	STEERING CONE	\$ 280.00	✓	
4	FRONT TYRES SHAFT	\$ 180.00	✓	
5	FRONT SPORT RIM	\$ 550.00	✓	
6	FRONT FENDER	\$ 300.00	✓	
7	FRONT DISC BRAKE	\$ 300.00	?	
8	FRONT BODY	\$ 600.00	✓	
9	FRONT PANEL COVER	\$ 280.00	✓	
10	HANDLE BAR	\$ 250.00	✓	
11	HANDLE BALANCER	\$ 150.00	✓	
12	BRAKE LEVER LEFT	\$ 150.00	✓	
13	FRONT SIGNAL LIGHT LEFT	\$ 280.00	✓	
14	INNER PANEL	\$ 400.00	✓	
15	INNER COMPARTMENT BOX	\$ 380.00	✓	
16	COMPARTMENT BOX COVER	\$ 280.00	?	
17	FRONT FOOTREST BOARD	\$ 320.00	✓	
18	FRONT FOOTREST RUBBER	\$ 200.00	✓	
19	FRON FOOTREST BOARD UNDER COVER L	\$ 200.00	✓	
20	MIRROR SET	\$ 250.00	✓	
21	MAINSTAND	\$ 280.00	x	
22	CVT COVER	\$ 480.00	✓	
23	REAR BOX	\$ 350.00	200 ✓	
24	REAR BOX BRACKET	\$ 400.00	✓	
25	EXHAUST PROTECTOR	\$ 280.00	x	
26	FRONT FORK REFLECTOR	\$ 100.00	✓	
27	BATTERY COVER	\$ 180.00	?	

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 12-Jul-23

Estimate no. 1291

Plate No. FBP6811D

Model.

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
28	FRONT CALIPER	\$ 17 350.00	X	
29	REAR CRASH BAR	\$ 27 400.00	—	
30	REAR FOOTREST BOARD LEFT	\$ 250.00	?	
31	BODY UNDER COVER	\$ 27 400.00	—	
32	COMPARTMENT BOX BRACKET	\$ 2 280.00	X	
33	AIR BOX COVER	\$ 27 200.00	—	
34	BODY ALIGNMENT	\$ 850.00	480	
35	SPRAY COVERSET	\$ 950.00	600	
36	ABS BRAKE PUMP	\$ 1,800.00	?	
37	HEAD LAMP	\$ 27 550.00	—	
38	FRONT FENDER INNER COVER	\$ 27 200.00	—	
39	LABOUR	\$ 900.00	400	

We, the undersigned hereby notify the Receiver of the following:

- The survey before/after spray painting
- The survey of damaged parts
- The survey is subject to confirmation
- The survey is on a "Winout Project" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 1,615.00
 \$ 16,150.00
 Sub Total : \$ 14,535.00
 GST 8% \$ 1,162.80
 Total: \$ 15,697.80

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.