



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Attention To:

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard #04-01
Suntec Tower Three
Singapore 038988

Vehicle Details

Make & Model : Toyota Dyna
Chassis No : JTFAT35Y10K215233
Registration No : GBK 5136 C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	Description	Qty	Amount (\$S)
1	Front door <i>Disturbed</i>		\$ 1,794.22
2	Front door top hinge <i>3 Bent</i>		\$ 78.50
3	Front door bottom hinge		\$ 78.50
4	Front door checker <i>set</i>		\$ 131.75
5	Front door weatherstrip <i>set</i>		\$ 149.60
6	Front door glass <i>Shattered</i>		\$ 448.55
7	Front door glass outer moulding <i>Disturbed</i>		\$ 205.70
8	Front door glass inner moulding <i>Disturbed</i>		\$ 122.65
9	Front door glass regulator gear <i>2 Disturbed</i>		\$ 295.65
10	Front door glass regulator motor		\$ 509.35
11	Front door glass channel <i>Bent</i>		\$ 245.30
12	Front door outer handle <i>new</i>		\$ 163.50
13	Front door inner trim <i>Disturbed</i>		\$ 897.50
14	Front door lock <i>Jammed</i>		\$ 375.85
15	Front door lock latch <i>new</i>		\$ 42.60
16	Front door inner handle <i>new</i>		\$ 86.95
17	Front door power motor control <i>new</i>		\$ 256.50
18	Front door inner pillar <i>3 Bent</i>		\$ 381.60
19	Front door outer pillar		\$ 398.70
20	Front door lower rubber <i>at</i>		\$ 83.50
21	Front door specker <i>new</i>		\$ 288.70
22	Front door frame rubber <i>at</i>		\$ 190.05
23	Front step garnish <i>Disturbed</i>		\$ 325.50
24	Front side mirror <i>new</i>		\$ 272.20
25	Front arch panel <i>Bent</i>		\$ 569.20
26	Front arch panel garnish <i>Disturbed</i>		\$ 122.80
27	Front seat belt <i>new</i>		\$ 497.12
28	Dash board <i>new</i>		\$ 973.40
29	Dash board side garnish <i>new</i>		\$ 164.70
30	Front windscreen glass moulding <i>new</i>		\$ 369.70
31	Front wiper panel <i>Disturbed</i>		\$ 594.60
32	Front panel <i>Disturbed</i>		\$ 1,313.74

33	Front panel emblem DYNA <i>me</i>		
34	Head lamp <i>cracked</i>	\$	69.74 ✓
35	Head lamp lower rubber <i>at</i>	\$	997.30 ✓
36	Front corner panel <i>distorted</i>	\$	47.20 ✓
37	Brake master pump <i>and</i>	\$	427.50 ✓
38	Brake booster pump <i>new</i>	\$	904.58 ✓
39	Brake fluid container <i>new</i>	\$	1,935.80 ✓
40	Brake booster pump bracket <i>but</i>	\$	225.60 ✓
41	Front bumper <i>distorted</i>	\$	134.50 ✓
42	Front bumper bracket <i>but</i>	\$	477.60 ✓
43	Front bumper fog lamp cover <i>distorted</i>	\$	212.70 ✓
44	Front grille <i>new</i>	\$	47.90 ✓
45	Front grille emblem LOGO <i>new</i>	\$	479.80 ✓
46	Rear cabin pillar <i>new</i>	\$	78.20 ✓
47	Rear cabin pillar inner trim <i>new</i>	\$	978.90 ✓
		\$	379.20 ✓

TOTAL LIST \$ 19,824.70
 25% 4956.18
\$ 14,868.53

S/N	Special Nett	Qty	Amount (S\$)
1	Front door inner trim clips <i>me</i>		\$ 50.00 ✓
2	Front wiper panel clips <i>me</i>		\$ 50.00 ✓
3	Front grille clips <i>me</i>		\$ 50.00 ✓
4	Rear cabin pillar inner trim clips <i>new</i>		\$ 50.00 ✓
5	Front windscreen pillar clips <i>me</i>		\$ 50.00 ✓
6	Brake fluid oil <i>me</i>		\$ 50.00 ✓
7	Head lamp lower rubber <i>new</i>		\$ 50.00 ✓

TOTAL SPECIAL NETT \$ 350.00

S/N	Labour	Qty	Amount (S\$)
1	Labour charge		\$ 1,500.00 ✓
2	Spray paint charge		\$ 1,500.00 ✓
3	Antirust		\$ 150.00 ✓
4	Rewire		\$ 100.00 ✓
5	R&R dash board		\$ 300.00 ✓
6	R&R brake master pump assy		\$ 300.00 ✓
7	R&R front windscreen glass		\$ 150.00 ✓
8	Transfer front door attachment		\$ 150.00 ✓
9	R&R rear inner trim for hot work repair.		\$ 300.00 ✓
10	Conduct a water leakage test		\$ 100.00 ✓
11	Redo the sealant on the gap to facilitate the repair		\$ 100.00 ✓
12	Refocus the headlamp beam		\$ 100.00 ✓

Admin
 13/07/23
 Not Authorized

TOTAL LABOUR \$ 4,750.00

TOTAL REPAIR COST **\$ 19,968.53**

Excess : To be advised