

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 17 Jul 2023

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Vehicle No | : GBK5136C | Accident Date | : 11/07/2023 |
| Make | : TOYOTA DYNA 150 | Policy No. | : - |
| Assignment Date | : 13/07/2023 | Excess | : S\$0.00 |
| Date of Inspection | : 13/07/2023 | Est. Duration of Repair | : 12 |
| Inspection At | : SV AUTOWORKS PTE LTD (HQ) 8 KAKI BUKIT AVENUE 4, #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 19,968.53 |
| Revised Amount | :S\$ | 11,707.24 |
| Check Items (Estimated) | :S\$ | 5,180.72 |
| Total | :S\$ | 16,887.96 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 98,000.00 |
| COE / PARF Rebate | :S\$ | 16,927.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 81,073.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.