



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/07/2023
Vehicle Reg. No.:	SLM4944P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MAZDA 2, 1.5 (A)	Vehicle Reg. Date:	24/04/2009
Vehicle Colour:	RED	Chassis No:	JMODE10Y190130709
Engine No:	ZY520362		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	5,597.00
Miscellaneous Items	0.00
Labour	1,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	6,977.00
+ GST 8.00% (\$)	558.16
Nett Amount (\$)	7,535.16

This claim is handled by: JUNIOR

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 13 Jul 2023)

Parts: 143

MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM4944P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>bl</i>	0.00	0.00	*900.00 F
2	1		*REAR BOOT LOGO <i>an</i>	0.00	0.00	*40.00 F
3	1		*REAR BOOT EMBLEM MAZDA 2 <i>an</i>	0.00	0.00	*50.00 F
4	1		*REAR WINDSCREEN MOULDING <i>an</i>	0.00	0.00	*100.00 F
5	1		*REAR WINDSCREEN SEALANT <i>an</i>	0	0.00	*40.00 FS
6	1		*REAR LAMP RH <i>?</i>	0.00	0.00	*400.00 F
7	1		*REAR BUMPER <i>de</i>	0.00	0.00	*780.00 F
8	<i>21</i>		*REAR BUMPER RETAINER L+R <i>RH an</i>	0.00	0.00	*60.00 F
9	1		*REVERSE SENSOR <i>an</i>	0	0.00	<i>200</i> *280.00 FS
10	1		*REAR BUMPER BRACKET RH <i>?</i>	0.00	0.00	*40.00 F
11	1		*REAR BUMPER REINFORCEMENT <i>bl</i>	0.00	0.00	*500.00 F
12	10		*REAR BUMPER CLIPS <i>an</i>	0	0.00	*20.00 FS
13	1		*REAR END PANEL <i>Repair</i>	0.00	0.00	*350.00 F
14	1		*REAR END PANEL TOP GARNISH <i>?</i>	0.00	0.00	*100.00 F
15	1		*REAR END PANEL COWLING RH <i>?</i>	0.00	0.00	*110.00 F
16	8		*REAR FENDER COWLING CLIPS <i>an</i>	0	0.00	<i>10</i> *18.00 FS
17	1		*REAR OUTER EXHAUST PIPE <i>X</i>	0.00	0.00	*700.00 F
18	1		*REAR TYRE RH <i>X</i>	0	0.00	*280.00 FS
19	1		*REAR FENDER INNER PANEL RH - REPAIR	0.00	0.00	-
20	1		*REAR TYRE RIM RH <i>X</i>	0.00	0.00	*380.00 F
21	1		*REAR FENDER RH - REPAIR	0.00	0.00	-

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 5,146.00
+ Margin on L,N Items 10.00% (\$\$) 451.00
Total Parts (\$\$) 5,597.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REPAIR PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	New	500	500.00
2	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR FENDER RH	New	600	600.00
3	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT	New	X	80.00
4	TO CHECK ELECTRICAL & WIRING SYSTEM FOR PROPER FUNCTIONING	New	30 28	100.00
Gross Labour Cost (\$\$)				1,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid
Ap 90010068
6 days
4/8
14/07/23
Resy after
Repair