

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2042E

Make : HYUNDAI

Model : IONIQ(G2)

Date: 12/07/2023

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10 <i>de</i>
10	FRT BUMPER CLIPS			\$ 22.00 <i>de</i>
1	FRT BUMPER SIDE BRACKER RH			\$ 28.00 <i>de</i>
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50 <i>de</i>
1	HEADLAMP RH			\$ 2,110.30 <i>de</i>
1	FRT BUMPER SIDE MOULDING RH			\$ 93.60 <i>de</i>
1	FRT FENDER RH			\$ 588.80 <i>de</i>
1	DAYLIGHT RH			\$ 642.50 <i>nn</i>
1	FRT FENDER BLUE-DRIVE EMBLEM RH			\$ 26.60 <i>de</i>
	SUB TOTAL		3718.90	\$ 4,361.40
	LESS 20%		2975.12	\$ 872.28
	DISCOUNTED TOTAL			\$ 3,489.12
	RENEW ADVERTISEMENT STICKER		100	\$ 100.00 <i>na</i>
				\$ 100.00
	Labour Charge			
	PANEL BEATING			\$ 750.00 <i>350</i>
	SPRAY PAINTING CHARGE			\$ 600.00 <i>500</i>
	CHECK ALL LIGHTING		880	\$ 60.00 <i>30</i>
	TOTAL LABOUR		3955.12	\$ 1,410.00
	ESTIMATE TOTAL		1/s\$3150 2 days #	\$ 4,999.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
up' 12/7/23 @ 3pm
1/s resurvey after repair
Tanpin @ 11h30am
2 days