

ASS. REC. BY:

REF:

MS/23007136/knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

857K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

30

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCT 8831X Yr Regn: 12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel c.c. 1896

Colour

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

467399 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

9/7/23

Rear

R/Bal.

9

mm

L/Bal.

9

mm

D.O.I.

17/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

118 21st & 600th Cntr (Red. \$ 6569.50, 5270)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	688R
Vehicle Details	
Vehicle No.:	SLJ8831X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jul 2023
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4407654
Chassis No.:	RU11207651
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,611.00
Original Registration Date:	29 Dec 2016
First Registration Date:	29 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$12,256.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2026
PARF Rebate Amount:	\$7,966.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$17,145.00
Total Rebate Amount:	\$25,111.00

The information contained herein is correct as at 13 Jul 2023

OK

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2005760554	Date of Loss:	09/07/2023
Vehicle Reg. No.:	SLJ8831X	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CAR4LEASE PTE LTD	Contact No:	+6598592417
Driver:	TAY SIEW CHOO		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	29/12/2016
Vehicle Colour:	Blue		
Engine No:	L15B4407654	Chassis No:	RU11207651
Odometer:	467397 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) ~~12~~ **5 days**

*Not Authorised
11 Days @ 6000
Returning After Paint
ET @ 2000*

Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	9,674.50
Miscellaneous Items	185.00
Labour	2,710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,569.50
+ GST 8.00% (S\$)	1,005.56
Nett Amount (S\$)	13,575.06

This claim is handled by: **HENRY LEE YOON SANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jul 2023)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SLJ8831X/13/07/2023 17:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	Bu *260.00 F	/
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	Di *30.00 F	/
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	Di *30.00 F	/
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	R *240.00 F	/
5	1		*FRONT BUMPER LOWER LIP GARNISH	0.00	0.00	Di *180.00 F	/
6	1		*BONNET	0.00	0.00	R *480.00 F	/
7	1		*BONNET HINGE RH	0.00	0.00	Di *45.00 F	/
8	1		*BONNET HINGE LH	0.00	0.00	R *45.00 F	/
9	1		*BONNET LOCK	0.00	0.00	Di *105.00 F	/
10	1		*BONNET INSULATOR	0.00	0.00	CM *100.00 F	/
11	1		*BONNET STAND	0.00	0.00	R *35.00 F	X
12	1		*FRONT GRILLE BASE	0.00	0.00	CM *230.00 F	/
13	1		*FRONT GRILLE CHROME MOULDING	0.00	0.00	CM *250.00 F	/
14	1		*FRONT LOWER GRILLE	0.00	0.00	Sm *90.00 F	X
15	1		*FRONT GRILLE CENTER BRACKET	0.00	0.00	CM *35.00 F	/
16	1		*FRONT GRILLE BADGE	0.00	0.00	Bu *25.00 F	/
17	1		*FRONT SUPPORT PANEL CPL	0.00	0.00	R *420.00 F	/
18	1		*FRONT PANEL UPPER GARNISH	0.00	0.00	Sm *70.00 F	X
19	1		*FRONT FENDER RH	0.00	0.00	R *240.00 F	X
20	1		*FRONT FENDER LH	0.00	0.00	R *240.00 F	X
21	1		*FRONT FENDER ACRH MOULDING RH	0.00	0.00	Sm *70.00 F	X
22	1		*FRONT FENDER ACRH MOULDING LH	0.00	0.00	Bu *70.00 F	/
23	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	Sm *105.00 F	X
24	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	Sm *105.00 F	X
25	1		*WIPER GARNISH	0.00	0.00	Sm *190.00 F	X
26	1		*HEADLAMP ASSY RH	ng cm 0.00	0.00	*1,150.00 F	/
27	1		*HEADLAMP ASSY LH	ng cm 0.00	0.00	*1,150.00 F	/
28	1		*HEADLAMP UPPER BRACKET RH	0.00	0.00	R *25.00 F	/
29	1		*HEADLAMP UPPER BRACKET LH	0.00	0.00	R *25.00 F	/
30	1		*HEADLAMP LOWER BRACKET RH	0.00	0.00	Di *35.00 F	/
31	1		*HEADLAMP LOWER BRACKET LH	0.00	0.00	Di *35.00 F	/
32	1		*FOG LAMP COVER RH	0.00	0.00	Sm *30.00 F	X
33	1		*FOG LAMP COVER LH	0.00	0.00	Sm *30.00 F	X
34	1		*RADIATOR ASSY	0.00	0.00	Bu *890.00 F	/
35	1		*RADIATOR AIR GUARD RH	0.00	0.00	Sm *40.00 F	X
36	1		*RADIATOR AIR GUARD LH	0.00	0.00	Sm *40.00 F	X
37	1		*CONDENSOR ASSY	0.00	0.00	R *480.00 F	/
38	1		*FAN SHROUD	0.00	0.00	Sm *90.00 F	X
39	1		*FAN SHROUD - RADIATOR	0.00	0.00	Sm *90.00 F	X
40	1		*WASHER TANK	0.00	0.00	Sm *75.00 F	X
41	1		*AIR DUCT	0.00	0.00	Sm *55.00 F	X
42	1		*AIR HOSE	0.00	0.00	Sm *45.00 F	X
43	1		*ENGINE LOWER COVER	0.00	0.00	Sm *120.00 F	X
44	1		*ENGINE LOWER SIDE COVER RH	0.00	0.00	Sm *65.00 F	/
45	1		*AIR INTAKE MANIFOLD ASSY	0.00	0.00	Sm *385.00 F	X
46	1		*AIR INTAKE MANIFOLD HOSE	0.00	0.00	Sm *25.00 F	X
47	1		*ENGINE MOUNTING RH	0.00	0.00	Sm *140.00 F	X

48 1

*ENGINE MOUNTING BRACKET RH

0.00

0.00

Su *85.00 F X

F=Franchise part.

Sub Total (\$\$)	8,795.00
+ Margin on L,N Items 10.00% (\$\$)	879.50
Total Parts (\$\$)	9,674.50

Ding Auto Pte Ltd/SLJ8831X/13/07/2023 17:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT BUMPER, GRILLE, INNER SHIELD & GARNISH/PANEL - CLIPS	150.00 <i>Mc 500</i>
2	1	FRT NUMBER PLATE & FRAME	35.00 <i>217 ✓</i>
Sub Total (S\$)			185.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00 <i>600</i>
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FT DOOR X2 & SUPPORT PANEL	New	1,200.00 <i>800</i>
3	REMOVE & INSTALL - RADIATOR & CONDENSOR COMPONENTS	New	150.00 <i>100</i>
4	REFILL - RADIATOR COOLANT	New	80.00 <i>501</i>
5	REFILL - AIR COND GAS	New	80.00 <i>X</i>
Gross Labour Cost (S\$)			2,710.00

Ding Auto Pte Ltd/SLJ8831X/13/07/2023 17:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >