

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 19 Jul 2023

Preliminary Advice

Vehicle No	: GBL9578D	Accident Date	: 11/07/2023
Make	: TOYOTA HIACE	Policy No.	: SP2002749495
Assignment Date	: 14/07/2023	Excess	: S\$2,000.00
Date of Inspection	: 18/07/2023	Est. Duration of Repair	: 5
Inspection At	: FORZA AUTOHAUS PTE LTD (HQ) NO.39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,347.50
Revised Amount	:S\$	7,230.50
Check Items (Estimated)	:S\$	3,937.00
Total	:S\$	11,167.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	117,000.00
COE / PARF Rebate	:S\$	49,916.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,084.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .