

Forza Autohaus Pte Ltd (Co.Reg.No:201833292C)

No.39 Woodlands Close, #01-34/35, Mega@Woodlands

Singapore 737856

Tel: 6278 1889 Email: enquiry@forzaauto.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002749495	Date of Loss:	11/07/2023
Vehicle Reg. No.:	GBL9578D	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CAR(S) LEASING PTE LTD	Contact No:	+6582984337
Driver:	TEH KIAP KANG		

Make/Model:	TOYOTA HIACE, 2.8 D DX (A)	Vehicle Reg. Date:	23/08/2022
Vehicle Colour:	BLACK/WHITE	Chassis No:	GDH2012021317
Engine No:	1GD8770763		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	12

Present Location: FORZA AUTOHAUS PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		9,377.50
Miscellaneous Items		0.00
Labour		2,970.00
Paintwork Labour		0.00
Towing		0.00
Calculated Gross Total (S\$)		12,347.50
- Excess (S\$)		2,000.00
(S\$)		10,347.50
+ GST 8.00% (S\$)		827.80
Nett Amount (S\$)		11,175.30

This claim is handled by: LIEW SHAN QI

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 213

Labour: Repairer's

Print Code: Forza Autohaus Pte Ltd/GBL9578D/13/07/2023 15:18

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>cm</i>	0.00	0.00	*380.00 F
2	1		*FRONT BONNET LOGO EMBLEM <i>cc</i>	0.00	0.00	*55.00 F
3	2		*FRONT BONNET HINGE L/R <i>?</i>	0.00	0.00	*240.00 F
4	1		*FRONT CORNER PANEL LH <i>de</i>	0.00	0.00	*165.00 F
5	1		*FRONT BONNET MECHANISM LOCK SET <i>bt</i>	0.00	0.00	*175.00 F
6	1		*FRONT GRILE ASSEMBLY <i>mc</i>	0.00	0.00	*380.00 F
7	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*420.00 F
8	2		*FRONT LED HEADLAMP <i>lh-br</i>	0.00	0.00	*2,700.00 F
9	1		*FRONT LED HEADLAMP CONTROL MODULE LH <i>br</i>	0.00	0.00	*380.00 F
10	1		*FRONT SUPPORT PANEL <i>bt</i>	0.00	0.00	*480.00 F
11	1		*FRONT HEADLAMP PANEL LH <i>?</i>	0.00	0.00	*210.00 F
12	1		*FRONT WIPER PANEL <i>de</i>	0.00	0.00	*220.00 F
13	1		*AIRCON CONDENSER <i>?</i>	0.00	0.00	*480.00 F
14	1		*RADIATOR <i>?</i>	0.00	0.00	*320.00 F
15	1		*AIRCON FAN HOUSING <i>?</i>	0.00	0.00	*360.00 F
16	1		*AIRCON BLOWER MOTOR <i>?</i>	0.00	0.00	*280.00 F
17	1		*DASH BOARD <i>?</i>	0.00	0.00	*685.00 F
18	1		*DASH BOARD SUPPORT <i>?</i>	0.00	0.00	*595.00 F

F=Franchise part.

Sub Total (S\$)	8,525.00
+ Margin on L,N Items 10.00% (S\$)	852.50
Total Parts (S\$)	9,377.50

Forza Autohaus Pte Ltd/GBL9578D/13/07/2023 15:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO REMOVE AND CHANGE AIRCON PARTS PLUS AIRCON GAS TOP UP	New	120? 180.00
2	TO REMOVE AND REFIX DASHBOARD PANEL	New	150? 300.00
3	TO PROVIDE LABOUR, WORKSMANSHIP TO CHANGE ABOVE DAMAGED BODYPARTS, REPAIR AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO ACCIDENT	New	700 1,200.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHEEL CONSISTENT TO ACCIDENT	New	600 1,200.00
5	TO CHECK WIRING AND RESETTING HEADLAMP FOCUSING	New	40 120.00
Gross Labour Cost (\$)			2,970.00

Forza Autohaus Pte Ltd/GBL9578D/13/07/2023 15:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
He 90010068
5 days
L/S
18/07/23
EXCESS: 2000
Repair
Resurvey after repair