



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: MARCUS XIAO			Ref: CS3/INC23005495/Tvy3e2-1 Date: 26/07/2023 Code: INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKB 9652T	Veh. Inspected	SKR 3529Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1224419-002	Excess (\$)	0.00	
Assign From		Assign Date	13/07/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2050402R042685	Colour	SILVER	
Odometer	133881 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/05/2023	Inspection Date	06/06/2023	
Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD 8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	