



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983			Ref: CS3/HSB23007145/Kvp3 Date: 14/07/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHA 8704A	Veh. Inspected	SNG 2890G	
Policy No.		Coverage (\$)	0.00	
Claim No.	S3M04O0X	Excess (\$)	0.00	
Assign From	LOH CYNTHIA	Assign Date	14/07/2023	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/07/2023	Inspection Date	14/07/2023	
Survey held at	AT PERFORMANCE 160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				