

ASS. REC. BY:

REF:

AISI 2300 7153/Kgp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.31%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 69476

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo S60 T5

c.c

1969

Colour:

N. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

118135

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

YV11FS 40LDG 2406597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

235/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

7

mm

L/Bal.

6 mm

L/Bal.

7

mm

D.O.A.

11/7/23

D.O.A.

17/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Wkspg sent to 2nd party for this veh.

2717 @ 6274.90 Carbur used to 3024, 33%

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MER-D

Lump Sum / I.B.I: (\$

6274.90

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Your Reference : SP2004601407-01

Accident Date : 11-Jul-2023

Our Ref : 023146 / CHAN

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

Singapore 068897

No. : 06877

Date : 13-Jul-2023

PAGE : 1

*NOT Notified
Punery B& NGIM
3 days Ex @ 600h*

ESTIMATED COST OF REPAIR FOR VOLVO S60 SLA6947G

=====

1 pc Front grille assy
1 pc Front grille air cowling
1 pc Front bumper fascia
1 pc Front bumper reinforcement
1 pc Front bumper sponge
2 pcs Front bumper side retainer
7 pcs Front bumper top clip
1 pc N/s headlamp assy

CM	780.00	✓
Sm	750.00	X
B1	1,900.00	✓
R	1,300.00	X
CM	500.00	✓
Sm	240.00	X
na	49.00	✓
ngim	1,900.00	✓
	7,419.00	
Add: 10% :	741.90	

1 pc Front no.plate with box

na 8,160.90 *45sn*
50.00 sn

To putty and spray replaced parts

500.00 *25cl*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.00 *25cl*

Total : S\$ 9,210.90

=====

Singapore Dollars Nine Thousand Two Hundred and
Ten and Cents Ninety Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: