

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0662/2023/EQ
DATE : 14-Jul-23
WIP : 28998

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/7/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HUANG QINAN
ADDRESS : BLK 203D COMPASSVALE ROAD
#14-57
SINGAPORE 544203
TELEPHONE : HP +65 96884230
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700087254-04
VEHICLE NO : **SLU 6656 R**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 11/12/2017
ENGINE NO : CVN 045372
CHASSIS NO : WAUZZZF42JA023431
MILEAGE : -
DATE IN : 14-Jul-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jul-23
PLACE OF ACCIDENT : BUKIT TIMAH ROAD AND FIRST AVE JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 6656 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW VEHICLE FROM SCENE OF ACCIDENT.	S/N	TBC	
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$	280.00	
3	TO REMOVE AND TRANSFER BOTH HEADLIGHTS' CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	
4	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FAN AND CONTROL UNIT. TO CARRY OUT VACCUM AND REGAS, AND PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00	
5	TO DISMANTLE RHS FRONT DOOR PANEL TRIM, REMOVE AND INSTALL WING MIRROR ASSY. RENEW DAMAGED TRIMS.	S/N \$	480.00	
6	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT HEADLIGHTS. RENEW FRONT LOCK CARRIER. REPAIR RHS FENDER TOP SUPPORT. RENEW DAMAGED PANELS, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$	7,000.00	
TOTAL LABOUR CHARGES		:	\$ 9,860.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 6656 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS FRONT DOOR, RHS FENDER TOP SUPPORT AND RHS A-PILLAR.	\$ 9,000.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 19,052.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 6656 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,515.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 641.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 231.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 269.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 75.00	
7	RADIATOR GRILLE	1	\$ 1,310.00	
8	FRONT BUMPER FOAM FILLER PIECE	1	\$ 147.00	
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 953.00	
10	FRONT BUMPER BRACKET - LH / RH	2	\$ 538.00	
11	FRONT BUMPER SUPPORT - LH / RH	2	\$ 68.00	
12	FRONT BUMPER BRACKET	1	\$ 163.00	
13	FRONT BUMPER TOP COVER	1	\$ 151.00	
14	CAUTION SIGN STICKER	1	\$ 17.00	
15	AIR CONDITIONER STICKER	1	\$ 9.00	
16	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00	
17	EXTERNAL TEMPERATURE SENSOR	1	\$ 65.00	
18	A/C REFRIGERANT LINE SEAL RING	2	\$ 26.00	
19	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	
20	FRONT FENDER - LH / RH	2	\$ 1,824.00	
SUB TOTAL SPARE PARTS		:	\$ 9,194.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 6656 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS - LH / RH	2	\$ 475.00	
22	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 172.00	
23	FRONT FENDER BRACKET - LH / RH	2	\$ 88.00	
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH	2	\$ 118.00	
25	FRONT FENDER RIVET	12	\$ 48.00	
26	FRONT FENDER BRACE - LH / RH	2	\$ 280.00	
27	FRONT FENDER LEDGE COVER - LH / RH SHORT	2	\$ 54.00	
28	FRONT FENDER LEDGE COVER - LH / RH LONG	2	\$ 74.00	
29	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 318.00	
30	BONNET	1	\$ 3,489.00	
31	BONNET ATTACHMENT PARTS	1	\$ 455.00	
32	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 101.00	
33	BONNET HINGE - LH / RH	2	\$ 722.00	
34	BONNET GAS FILLED STRUT	1	\$ 136.00	
35	BONNET STRIKER - LH / RH	2	\$ 120.00	
36	BONNET LOCK - LH / RH	2	\$ 481.00	
37	BONNET BOWDEN CABLE - CENTER	1	\$ 67.00	
38	BONNET RELEASE CABLE COVER	1	\$ 12.00	
39	BONNET BOWDEN CABLE	1	\$ 67.00	
40	FRONT PLENUM CHAMBER COVER	1	\$ 115.00	
SUB TOTAL SPARE PARTS		:	\$ 7,392.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 6656 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WHEEL SPOILER - LH / RH	2	\$ 174.00	
42	FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH	2	\$ 120.00	
43	FRONT WHEEL HOUSING LINER - LH	1	\$ 281.00	
44	FRONT WHEEL HOUSING LINER - RH	1	\$ 277.00	
45	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH / RH	2	\$ 316.00	
46	HEADLIGHT - LH / RH	2	\$ 17,574.00	
47	HEADLIGHT POWER MODULE - LH / RH	2	\$ 1,831.00	
48	HEADLIGHT CONTROL UNIT - LH / RH	2	\$ 1,731.00	
49	HEADLIGHT HOSE - LH / RH	2	\$ 86.00	
50	LIFT CYLINDER BRACKET - LH / RH	2	\$ 15.00	
51	LIFT CYLINDER - LH / RH	2	\$ 488.00	
52	LIFT CYLINDER CORRUGATED PIPE	1	\$ 111.00	
53	LOCK CARRIER	1	\$ 1,569.00	
54	LOCK CARRIER SUPPORT - LH / RH	2	\$ 90.00	
55	RADIATOR AIR GUIDE - LH INNER	1	\$ 38.00	
56	RADIATOR AIR GUIDE - LH OUTER	1	\$ 25.00	
57	RADIATOR AIR GUIDE - RH INNER	1	\$ 38.00	
58	RADIATOR AIR GUIDE - RH OUTER	1	\$ 25.00	
59	RADIATOR AIR GUIDE - UPPER	1	\$ 25.00	
60	RADIATOR AIR GUIDE - LOWER	1	\$ 38.00	
SUB TOTAL SPARE PARTS		:	\$ 24,852.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 6656 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	A/C CONDENSER WITH DRYER	1	\$ 724.00	
62	A/C CONDENSER O-RING	1	\$ 13.00	
63	A/C CONDENSER SEAL RING	1	\$ 14.00	
64	A/C CONDENSER SEAL RING	1	\$ 13.00	
65	A/C REFRIGERANT LINE RESSURE SENSOR	1	\$ 213.00	
66	A/C SERVICE VALVE CORE	1	\$ 57.00	
67	RADIATOR	1	\$ 718.00	
68	RADIATOR LOWER RUBBER BUSH - UPPER	2	\$ 20.00	
69	RADIATOR LOWER RUBBER BUSH - LOWER	2	\$ 28.00	
70	ADDITIONAL RADIATOR - LOWER CENTRE	1	\$ 560.00	
71	RADIATOR SECURING PIN - UPPER	2	\$ 6.00	
72	READY-MIX COOLANT	4	\$ 217.00	
73	RADIATOR FAN WITH CONTROL UNIT	1	\$ 2,504.00	
74	INTAKE AIR DUCT - RH LOWER	1	\$ 38.00	
75	INTAKE AIR DUCT - CENTER	1	\$ 67.00	
76	AIR FILTER	1	\$ 443.00	
77	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH	2	\$ 728.00	
78	FRONT WINDOW GUIDE - RH	1	\$ 551.00	
79	FRONT NUMBER PLATE	S/N	\$ 60.00	
80	SUNDRIES		\$ 1,000.00	
TOTAL SPARE PARTS		:	\$ 49,412.00	
TOTAL LABOUR CHARGES		:	\$ 19,052.00	
GRAND TOTAL		:	\$ 68,464.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT