

(08/11/13) wof

ASS. REC. BY: *Paul*

REF:

NS/INC 23007162/RVY3

369K

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 5718A

at Workshop m/s

SMART

of

Woolloomooloo

Insured:

NTME

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 5718A

Yr Regn: 2020 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIMS ABA

c.c 1798

Colour

MAROON

A/C: Insured / Std / NI / NA

Sp. Reading

187423

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU503091716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILUN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/07/23

D.O.I.

14/07/23

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐  
☐  
☐  
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) )

TOTAL

31

## SMRT Accident Vehicle Repair Estimates


ADV - R1

## Section A - Accident Details

Registration Number	SHB5718A
Case Reference Number	TAX/07/23/2014
Registration Date	1/12/20
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	KELVIN LIONG KIN CHUNG (KELVIN LIANG JIANCONG)
Type of Accident	Head To Side
Accident Date and Time	6/7/23 7:30 AM
Accident Reported Date and Time	6/7/23 12:01 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118862
Special Instruction to ARC, if any	front right portion damaged/ right side mirror damaged ( pls chk)
Prepared Date and Time	14/7/23 1:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,416.00	\$0.00
Total Spare Part Cost	\$7,141.51	\$0.00
Total Other Cost	\$1,114.44	\$0.00
<b>TOTAL COST</b>	<b>\$10,516.95</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$10,500.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	14/07/2023 1:13 PM	
Signature		x) Rasmie - Hp 90010068 5 days / L/S 14/07/23 Resum after repair
Remarks		

## Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

FAX

Estimate

Accident

Date Generated

User ID

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	<del>845</del> 400
Total Labour	\$845.00	

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	200
TO RESPRAY FRONT FENDER RH	\$378.00	200
TO RESPRAY VIEW MIRROR	\$220.00	<del>220</del> 50
RESPRAY WHEEL CAP	\$220.00	X
TO RESPRAY RIM	\$220.00	X
Total Spray Painting & Panel Beating	\$1,416.00	

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$56.00	X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	<del>100</del> 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	60
TO REMOVE AND REFIT TYRE	\$120.00	X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$148.44	148.44
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	X
TO REPLACE SUNDRY PARTS	\$100.00	X
Total Other Costs	\$1,114.44	

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	Sal
		52115-47050	SUPPORT, FR BUMPER RH	1.00	\$86.20	25.00	\$64.65	Replace	9
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	MC
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$103.70	25.00	\$77.78	Replace	X
		81145-47890	UNIT, HEADLAMP, RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	X
		53801-47080	FENDER SUB-ASSY, FR, RH	1.00	\$1,060.70	25.00	\$795.53	Replace	St
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	MC
		53875-47120	LINER, FR FENDER, RH	1.00	\$219.10	25.00	\$164.33	Replace	X
		53857-12010	RETAINER, FR WHEEL RH	1.00	\$3.50	25.00	\$2.63	Replace	X
		53827-47050	PROTECTOR, FR FENDER RH	1.00	\$101.80	25.00	\$76.35	Replace	X
		53851-47061	PAD, FR WHEEL RH	1.00	\$65.00	25.00	\$48.75	Replace	X
		42611-47450	WHEEL, DISC FRONT	1.00	\$2,036.30	25.00	\$1,527.23	Replace	X
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$171.75	Replace	Sal
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	X
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	X
		45046-49255	END SET, TIE ROD, RH	1.00	\$202.30	25.00	\$151.73	Replace	X
		48068-47060	LOWER ARM SUB-ASSY, FRONT RH	1.00	\$823.20	25.00	\$617.40	Replace	X

## SMRT Accident Vehicle Repair Estimates

SMRT Auton  
80 Woodland  
FAX Number  
Estimator Tel  
Accident Rep

Date Genera  
User ID

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		87910-47450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,556.00	10.00	\$1,400.40	Replace	X
		87915-47070-A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	25.00	\$88.35	Replace	Repair
Total					\$10,935.34		\$8,926.89		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
Total									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5718A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2020
Engine No.:	2ZR2G85144
Chassis No.:	JTDKB3FU503091716
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	01 Dec 2020
First Registration Date:	01 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2028
PARF Rebate Amount:	\$10,897.00
COE Expiry Details	
COE Expiry Date:	30 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,843.00
COE Rebate Amount:	\$20,040.00
<b>Total Rebate Amount:</b>	<b>\$30,937.00</b>
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jul 2023

OK