

INSPECTION REPORT

Hotwheelz

23 Kaki Bukit Rd 4, #01-11 Synergy@KB Bedok, Singapore 417800

Accident Date:	14/07/2021	Inspection Date:	20/04/2022	Report Date:	11/08/2021
Place of Inspection:	Hotwheelz	Our Ref:	AVS2022-30654/ID	Your Ref:	SH9740X
	23 Kaki Bukit Rd 4, #01-11 Synergy@KB Bedok, Singapore 417800	Claimant:	Lee Wen Jie		

Description of Vehicle:

Veh. No:	FBR6863T	Make/Model:	Yamaha R15 ABS Manual
Colour:	Black	Engine No:	G3N4E0029462
Engine Capacity:	155 cc	Chassis No:	ME1RG6713L0024987
Odometer:	NA	Reg. Date:	26/09/2020



Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	No
Air-Conditioner:	NA	Radio/Cassette/CD:	No	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Fair
Tyre Make:	MRF				
Front Tyre Size:	100/80-17	Front Side:	4mm		
Rear Tyre Size:	140/70-17	Rear Side:	4mm		

Description of Damage:

The damage was found on the both multiple portions.

Point of Impact:



08 MAY 2023

Adjuster: Muhammad Idram
Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

Adjustment of Repair Cost for Vehicle:		FBR6863T		Our Ref: AVS2022-30654/ID	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Front fender	Repair	145.00	-- X nn
2	1	Front wheel axle	Distorted	75.00	75.00 X nn
3	1	Front brake disc	Grazed	155.00	155.00 X nn
4	1	Windshield	Grazed	115.00	115.00 X nn
5	1	Headlamp cowling	Broken	450.00	450.00 ✓
6	1	Headlamp	Broken	515.00	515.00 X nn
7	1	Front signal lamp set of 2	Broken	85.00	85.00 ✓
8	1	Front side mirror set of 2	Grazed	115.00	115.00 ✓
9	1	Digital meter	Scratches	650.00	650.00 X nn
10	1	Handle clip set of 2	Bent	220.00	220.00 ✓
11	1	Handle clip balancer set of 2	Grazed	55.00	55.00 ✓
12	1	Steering stem bearing	Necessary	90.00	90.00 X nn
13	1	Front fork steering fork bridge	Re-use	380.00	-- X nn
14	2	Front fork steering stem	Distorted	350.00	350.00 X nn
15	2	Front top cowling inner L/R	Broken	225.00	225.00 ✓
16	2	Side fairing inner L/R	Broken	315.00	315.00 ✓
17	2	Side fairing outer L/R	Broken	420.00	420.00 ✓
18	1	Decal set	Necessary	200.00	200.00 120 ✓
19	1	Brake lever	Grazed	58.00	58.00 ✓
20	1	Clutch lever	Grazed	58.00	58.00 ✓
21	1	Front footrest L/R	Grazed	115.00	115.00 ✓
22	2	Front footrest holder L/R	Grazed	155.00	155.00 X nn
23	1	Brake pedal	Grazed	68.00	68.00 ✓
24	1	Gear pedal	Bent	72.00	72.00 ✓
25	1	Tank cover L/R	Deformed	250.00	250.00 X nn
26	1	Tank cover centre	Re-use	115.00	-- X nn
27	1	Tail outer cover L/R	Repair	225.00	-- X nn
28	1	Rear footrest set of 2	Grazed	115.00	115.00 X nn
29	2	Rear footrest holder L/R	Bent	185.00	185.00 X nn
30	1	Exhaust pipe	Dented	650.00	650.00 X R

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Adjustment of Repair Cost for Vehicle:			FBR6863T	Our Ref: AVS2022-30654/ID	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
31	1	Exhaust pipe cover 1	Grazed	65.00	65.00 ✓
32	1	Exhaust pipe cover 2	Grazed	75.00	75.00 ✓
33	1	Exhaust pipe cover 3	Broken	60.00	60.00 ✓
34	1	Rear swing arm	Grazed	520.00	520.00 ✓
35	1	Rear mudguard	Grazed	105.00	105.00 ✓
36	1	Rear brake disc	Warped	175.00	175.00 ✗ nn
37	1	Rear wheel axle	Distorted	105.00	105.00 ✗ nn
38	2	Wheel rim set of 2	Distorted	450.00	450.00 ✗ nn
39	2 1	Wheel bearing F/R	Necessary	116.00	116.00 58 ✓
Sub Total:				8,297.00	7,432.00
3259 -10% 2933.10 Discount (less 10%):				829.70	743.20
				7,467.30	6,688.80

Special Nett Items					
1	1	Rear box	Grazed	350.00	280.00 220
2	1	Rear box bracket	Bent	125.00	125.00 ✗ nn
3	1	Front number plate sticker	Necessary	15.00	15.00 ✗ nn
4	1	Front P plate sticker	Necessary	15.00	15.00 ✗ nn
Sub Total:				505.00	435.00
220 Total Parts Price:				7,972.30	7,123.80

Labour Cost				
1	Towing charges		100.00	---
2	Replace, realign and adjust above damaged parts, check wiring and lighting system.		700.00	500.00 300
3	To replace and balance front and rear wheel rims.		150.00	80.00 50
4	To knock, straighten chassis & body balancing.		450.00	320.00 150
5	To remove/refit, replace (if damage) check and straighten front fork tubes.		150.00	80.00 50
6	Spray painting.		600.00	500.00 200
Sub Total:			2,150.00	1,480.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Adjustment of Repair Cost for Vehicle:			FBR6863T	Our Ref: AVS2022-30654/ID	
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
Grand Total:				10,122.30	8,603.80

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$10,122.30 The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of S\$6,800.00.

We have not authorised the repair. Under normal circumstances, estimated seven (7) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.