

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:		v v v v v v v v v v v v v v v v v v v	
Type of Claim :	TP(UOI)	Vehicle No.	SLG3561Z
		Make & Model	TOYOTA CAMRY 2.5 AUTO
		Year of Manufacture	2016
		Chassis No.	MR053AK5004011404
Ins Company :	MSIG	Engine No.	2ARU337562
Excess :	1	Policy No.	:
Date of Accident :1	0.07.2023	Time of Accident	
Suggested Days of Repair:		In-house Vehicle Asses	ssor
Repair Estimates		Case Owner	: KELVIN
2 4 () 2 4 () 4 2 4 2		Signature	
Parts (a) Cost / List Price Items	\$ 33,192.00		
Plus/Less25%	\$ 8,298.00	Operation	
Total of Cost / List	\$ 24,894.00		36 E:kelvinsukwen@cdge.com.sg 3705 E:joharibh@sparkcarcare.com
(b) Nett Price Items			916 E: oisunpin@cdge.com.sg
Less			Not Adha
Total of Nett Item			118 0
(c) Special Nett Items	\$ 45.00		all the
Total Parts Cost (Appendix A)	\$ 24,939.00		NOT Nothersel USing 8 Merovey After Pa,
abour (Appendix B)	\$ 3,260.00		
otal Repair Cost	\$ 28,199.00		
he above total will be subjected t	to 7% G.S.T.		
Name of Surveyor		Kenner	- ' Y
Company		1.10%	
Survey conducted on	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	17/7/23 at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not au	uthorized until further notic	e.
(b) Recommended Days of Rep	The second of th	'	
(c) Resurvey	: Required / N		
(d) Excess	:\$		
		Le	e: 17/7/23_
(e) Signature of surveyor	:	Date	e:

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No
: SLG3561Z
Case Owner : KELVIN

Make & Model
: TOYOTA CAMRY 2.5 AUTO
Year Manufacture : 2016

Chassis No
: MR053AK5004011404
Engine No : 2ARU337562

Sales Order
: Supplier : TOYOTA CAMRY 2.5 AUTO

Order By : KELVIN Type of Claim : TP(UOI)

S/No	Part Description	QTY	Cost Price	List Price	S/N	Disposition By Surveyor
1	FRT BUMPER	1		850.00	A TOWNS TO STATE OF THE STATE O	
2	FRT RADIATOR GRILLE	1		\$ 1,250.00	41 6	
3	FRT BUMPER LOWER GRILLE	11	nu!	\$ 950.00		_
4	BUMPER LWR GRILLE CHROME GARNISH	1	cm	\$ 250.00	an Banda B	<u> </u>
5	FRT BUMPER SIDE GARNISH-LH	1 1	Bu	\$ 52.00		X
6	LHF BUMPER RETAINER	1	DIT	\$ 137.00	ATTENDED TO	
7	LHF FOG LAMP ASSY	1		\$ 430.00		?
8	FOG LAMP COVER -LH	1		\$ 78.00	A.	7
9	FOG LAMP COVER CHROME GARNISH	1		\$ 58.00	minutes of the same	-
10	FRT BUMPER SPONGE	1	Bo	\$ 135.00	A. S. Call and Act	1
11	FRT BUMPER REINFORCEMENT	1	ne estados en entre en estados en estados en estados en estados en estados en entre en estados en estados en estados en estados en estados en entre en estados en estados en entre entre en entre en entre en entre en entre entre en entre en entre ent	\$ 550.00		?
12	FRT SENSOR	1		\$ 468.00	Appendix and a second	7
13	FRT SENSOR BRACKET	4	ya Sandaya was	\$ 100.00		and the same of th
4 1	HF HEADLAMP	1	an	\$ 1,850.00	rig sagi	
5 L	HF HEADLAMP CHROME GARNISH	1		\$ 230.00		7
6 F	REAR TAILGATE	he produced and	R	\$ 1,550.00		
_	AILGATE WEATHERSTRIP	1	Distres	\$ 250.00	in the same	50%1
8 7	AILGATE INNER BOARD	1	ne torn	\$ 615.00	Contraction of the A	
_	AILGATE HINGE-LH	1		\$ 180.00	r d men fallen in	7
_	AILGATE HINGE-RH	1 1 min	and a top Strong Co. S.	\$ 180.00	place of the second	7
_	AILGATE LOCK	1	nu	\$ 515.00	and the second second	
_	AILGATE LATCH	· 1	The second second	\$ 35.00		7
1_	MBLEM "CAMRY"	1	Nec	\$ 65.00	e erene b	
-	MBLEM "TOYOTA	1	na	\$ 65.00	Separate Sep	
_	MBLEM "2.5"	1	na	\$ 65.00		
-	EAR NO.PLATE LIGHT GARNISH	1		\$ 185.00		7
_	O.PLATE LIGHT CHROME MLDG	1	Nul			
_		1	cm	\$ 420.00		-
_	HR OUTER TAILLAMP	Spire	cm	\$ 420.00		
-	HR INNER TAILLAMP HR OUTER TAILLAMP	1	em	-	THE RESERVE TO SERVE THE PARTY OF THE PARTY	of decisions

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SLG3561Z Case Owner : KELVIN

Make & Model : TOYOTA CAMRY 2.5 AUTO Year Manufacture : 2016

Sales Order : 0 Supplier : 0

Order By : KELVIN Type of Claim : TP(UOI)

S/No	Part Description	QTY	Cost Price		List Price	s	S/N	Disposition By Surveyor
31	LHR INNER TAILLAMP	1	CM	\$	420.00			
32	TAILLAMP SIDE CLIPS	2	M	\$	15.00			<u> </u>
33	REAR END PANEL	1	R	\$	910.00)
$\overline{}$	END PANEL TRIM BOARD	1	011	\$	398.00			
	SPARE TYRE COMPARTMENT	1	n	\$ 1	,105.00			X
_	SPARE TYRE TRIM BOARD	1		\$	625.00			?
37	REAR BUMPER REINFORCEMENT	1	R	\$	550.00		h De	
38	REAR BUMPER	1	By	\$	890.00	10 10		
39 l	REAR BUMPER CLIPS	10	Ma	\$	55.00		7	
40 F	RHR BUMPER RETAINER	1	Dis	\$	150.00		100	
\$1 L	LHR BUMPER RETAINER	1	DIY	\$	150.00			
12 F	REVERSE SENSOR	1	NU	\$	468.00			
3 8	SENSOR BRACKET	4	1 0 m - 1 1	\$	100.00			7
4 F	REVERSE CAMERA	w sp = 1 1 or	Re 3 Y	\$	250.00			.7
5 R	RHR BUMPER REFLECTOR	1	Sa	\$	78.00		V.	X
6 L	HR BUMPER REFLECTOR	1	Su	\$	78.00			X
R	EAR KEYLESS SENSOR	1		\$	245.00			7
FI	RT BUMPER CLIPS	10	na	\$	55.00	1		
RI	EAR NO.PLATE	1		Ť	R	\$	45.00	
\perp				1 4		le .		
L			are richall	91 DI I	iltants hence		ity	
L		4 - 4 - 3 -	 To resurvey 	before	lafter enray no	maine	14.00	
		100	Parts prices	a imale is	d nad/e) durin		rvey	(3 xy =
			 I hird party s 	urvev	S on a "Withou	Deal	edina to the state of	1.4
			i vo modal ilic	JE III IK "SAT	MODICAL SHOW			
			Supplements	me itaa	n(s) must be re oproval from In		yed and	N Part of the second
			Acknowledged				- Continue	, , , , , ,
	F F F - 42 1 - 5		Signature:		PERSONAL MARK			A Commence

Note: If any of the quoted parts are recommended to be repaired. Then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.	:	SLG3561Z	Case Owner	:	KELVIN	
Make & Model	:	OYOTA CAMRY 2.5 AUTO	Year of Manufacture	. 3	2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO PANEL BEAT ON FRT BUMPER,REAR BUMPER,REAR TAILGATE	\$ 1,500.00	12001
	REAR END PANEL,SPARE TYRE COMPARTMENT		_
2	TO RESPRAY ON FRT BUMPER,REAR BUMPER,REAR TAILGATE	\$ 1,500.00	12001
	REAR END PANEL, AFFECTED AREA		299
3	TO CHECK WIRING ;HEADLAMP,TAILLAMP.REVERSE SENSOR	\$ 120.00	801
4	TO REMOVE/REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM	\$ 80.00	
	TO ASSIST WORK LOAD	V 00.00	AND THE STATE OF T
			V. 1
5	TO TUFF COAT WELDING AREA	\$ 60.00	
\dashv		Harris Harris II	No.
\top			
		87	
\perp			
+		1	
\top			
_	The second s		
+			18 1 20 20 20 20
+			<u> </u>
+		40 1 11	
\top			Market or and her sin
			A A
1			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

23780001 / ComfortDelGro Engineering Pte Ltd [609286] RY DATE & TIME: 11/07/2023 11:24 (SGT) RMITTED BY: Nadirah Binte Mohamed Nasser RSION: 1 (11/07/2023 11:24 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to reposition policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/07/2023 11:24 (SGT) Reported by **Actual Driver Date of Accident** 10/07/2023 19:47 (SGT) **Exact Location of Accident** Keppel Rd Off Street (K 0108), Singapore Additional Location Information KEPPEL ROAD TOWARDS MCE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG3561Z

INSURED/POLICYHOLDER

Is company? MOHAMED SELAMAT BIN MOHAMED YUS AL-HAJI Name Of Registered Owner NRIC No SXXXX013G YANA_SARIBAN@TOACORP.COM.SG **Fmail Address** (Phone) +65-82651944 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Toyota Camry Model Variant Exact purpose for which vehicle was being used at time of **Employment** accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category Transmission Auto 2500

INSURANCE COMPANY

MSIG Insurance (Singapore) Pte. Ltd. Name of Insurance Company J 300479133 MCX Policy Number / Cover Note Number

DRIVER

MOHAMED SELAMAT BIN MOHAMED YUS AL-HAJI Name of Driver SXXXX013G NRIC No 11/04/1967 Date Of Birth Outdoor Occupation

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process. 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance 5. Any false reporting may be referred to the Police for investigation.

- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties. 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
- 8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that ;

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their On Persian firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VISION ENCHANGE #16-01/08, SINGAPORE 608526 TBL: 6775 5044-7 FAX: 6775 3542

Policyholder's Signature / Date &

Time 10:009M

110722

Driver's Signature (If driver is not the policyholder) / Date & Time 15: 5 5 5M

MADIRAHI

Witnessed by Reporting Centre Personnel

Sketch Plan

SMU 8350Y SLP 866K

Accident Happens At Keppel Road Towards MCE