NCVI INVOLVING 5 TON (MID 21277) AND CIVI VEHICLE (SMY9366A) ALONG TPE TOWARDS AIRPORT IN BETWEEN EXIT 4 AND EXIT 3CON 13 JULY 2023 AT ABOUT 1555HRS

Schematic Diagram




Figure A-1




Figure A-2




Figure A-3




Figure A-4




Figure A-5




Figure A-6




Figure A-7




Figure A-8



Figure B-1: Front view of MID 21277




Figure B-2: Rear view of MID 21277



Figure B-3: Side view of MID 21277



Figure B-4: Side view of MID 21277




Figure B-5: Zoom in view of SMY 9366A

SINGAPORE ARMED FORCES STATEMENT

RANK & NAMI	& NAME CPL TING GUANG SHENG						
NRIC	TXXXX6715E	AGE	20	GENDER	MALE		
NATIONALITY	SINGAPOREAN	TYPE OF SERVICE	NSF	DRIVING PERMIT NO.	SAF/TPT/N/011 89/22		
VOCATION	TRANSPORT OPERATOR	UNIT	T.H.E SELARANG	CONTACT			
DATE OF ENLISTMENT	120821	ORD	110823				
ADDRESS							
RECORDED BY	7	DATE		SIGN			
After the detail ended at around 1530H, I drove my 5 Ton back to Selarang camp from Pasir Ris camp. Along TPE towards Airport between exit 4 and exit 3C, I was driving at 55km/h on the third lane, when I saw road works ahead. I decided to make a lane change to the second lane. After I drove past the road works, I checked my blind spot mirror on the left to ensure the lane was safe to lane change. As I was about to lane change, I checked the left side again to ensure the lane was clear. While making a lane change, I slowed down as there were still many vehicles in front. This was when I felt an impact at my left-hand front. I realised that I came into contact and had side swiped a civilian Honda Shuttle (SMY9366A). After this, I parked my vehicle to a safe side, got down from my vehicle to check for injuries and damages before calling my superiors. This is all I have to say.							
DATE	130723	s	IGNATURE	9.3	Sheng		

Figure C-1: Statement of TO




Figure D-1: Police report Part 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20230713/7082

CONTINUATION OF REPORT

Driver						
Name	TING GUANG SHENG		ID No		715E	
Related Vehicle	SMY9366A (Lorry)		Conta	ct No.		
Hospital/Clinic	NIL		Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL	
Date	NIL		Date		NIL	
No. of Days granted Medical Leave NIL		Degree of		NIL		

Brief Details

On 130723 at about 1555H, I was en route from Pasir Ris camp to selarang camp to return back to unit. I was driving an empty 5 Ton (MID21277) alone on the Third Lane along TPE towards the airport when I noticed that there were road works on the Third Lane after Exit 4.

I made a lane change to the Second Lane. While driving along the Second Lane, I attempted to make a lane change after the road work back to the Third Lane.

While lane changing onto the Third Lane, I felt an impact on the left hand front of the 5 Ton and that was when I realised I had side swiped a civilian Honda Shuttle, License plate SMY9366A.

5Ton damage: left step ladder and left hand front signal light metal cage were scratched

Civilian vehicle: The right hand rear glass was shattered and right hand rear bumper was also dented and scratched

There were no injuries reported.

Figure D-2: Police report Part 2





3 of 3 Report No. T/20230713/7082

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/07/2023 20:28
Officer In Charge Of Case: TP / TPIB / LEE GUANG HUI Contact No.: 65476204	Classification Of Case:
NP168	70

Figure D-3: Police report Part 3