

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLV8776JNot Authorized
C/Ping &
Memory After Pain

4-5 days

No.	Qty	Nett Items	
1	1	Rear bumper	\$ Bu 707.60 ✓
2	2	Rear bumper side retainer	\$ R 50.00 X
3	2	Rear bumper lower bracket	\$ R 20.00 X
4	1 set	Rear bumper clips	\$ R 30.00 ✓
5	1	RH taillamp	\$ R 427.00 ✓
6	1	Rear tailgate	\$ R 1,004.70 ✓
7	1	Rear tailgate RH "RSZ" emblem	\$ R 51.40 ✓
8	1 set	Rear tailgate windscreen moulding	\$ R 105.00 ✓
9	1 set	Rear tailgate inner trim board clips	\$ R 60.00 X
10	1	Rear tailgate weatherstrip	\$ R 143.00 X
11	1	Rear end panel	\$ 357.00 ?
12	1	Rear end panel top garnish	\$ R 145.00 X
13	2	Rear RH lower exhaust silencer mounting	\$ R 76.00 X
Total :			\$ 3,176.70
<u>Special Nett Items</u>			
14	1 set	Rear bumper reverse sensor (C/w 4 pcs)	\$ 550.00 ?
15	1	Rear RH lower exhaust silencer	\$ 1,500.00 ?
16	1 set	Rear windscreen sealant	\$ R 50.00 40sm
17	1 set	Rear end panel sealant	\$ 50.00 ?
Total :			\$ 2,150.00
<u>Labour</u>			
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00 ?
2		To putty and spray Spray Paintings charges.	\$ 1,000.00 6001
3		To remove, refit rear windscreen.	\$ 150.00 1201
4		To check wirings and lightings.	\$ 40.00 201
5		To remove, refit both reverse sensors.	\$ 80.00 601
6		To remove, refit rear upholstery and attachments.	\$ 120.00 ?
7		To remove, refit rear lower exhaust silencer.	\$ 80.00 ?
8		To supply and apply anti rust treatment	\$ 80.00 301
Total :			\$ 2,550.00

Total Parts and Labour : \$ 7,876.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: