

Not Withheld  
Recovery B&Paint

**Trans-cab Auto Services Pte Ltd**

AAD2305-135

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5512X

Vehicle No.:

Chassis No.:

UEN No:

UEN No:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5512X

JTDKB3FU303092590

200303878K

TOYOTA

PRIUS GEN 4

27/5/2023

SKS4049D/China.

6/11/2020

**PART**

1 MIRROR ASSY, OUTER REAR VIEW, RH

**LIST**

	\$	1,814.09	✓
<b>TOTAL</b>	\$	<b>1,814.09</b>	
<b>25%</b>	\$	<b>453.52</b>	
	\$	<b>1,360.57</b>	

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To Check Electrical Lighting Concerned.	\$	170.00	151

**TOTAL** \$ **2,600.00**

**Over All Total** \$ **3,960.57**

**(PART-BY-PART) Repair Days**

**02 Days**

**1 day**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: